

Basic Condition Guide

| Report ID: | 27,796,349 | Version: | 1 | |
|------------|-------------|----------|---|--|
| Created: | 26 Nov 2025 | | | |

| | ullei | <u> </u> | | Created: 26 Nov 2025 | | | | |
|--|--|--------------------------|---------------------------|------------------------------|-----------------|-----------|----------|--|
| Make: | Holden | Model: | Spark | | | Requires | | |
| | Hatchback | Year: | 2016 | | OK | Attention | N/A | |
| Body Style: | KYJ234 | | 05 Oct 2026 | Engine | | | | |
| Rego No.: | 02 Dec 2025 | Rego Expiry: Odometer: | 71,322 Kms | Oil level | | | | |
| WoF Expiry: | | | | Smoke & fumes | / | | | |
| Good No.: | 27796349 | VIN: | KL3DC48A4GC521009 | Engine performance | ' | | | |
| Next Service: | 77,000 | Service History: | INO | Noise | / | | | |
| lote: This report is his report is a quide | only. Consideration is mad | e for age and mileage. P | Coolant condition | / | | | | |
| iagnostic testing ur | ndertaken. The vehicle has be ection prior to purchase an | oeen driven up to 50km/ | Cooling performance | / | | | | |
| (ey | , | | Radiator / Hoses (visual) | V | | | | |
| - | = Rust C = C | Crack *= Deca | Transmission | | | | | |
| | T = Paint defect P = P | | Operation | V | | | | |
| | | | | Noise | V | | | |
| S | | SPTP | SD | Clutch | | | 1 | |
| | | | S | CV joints | V | | | |
| | | | | Wheel bearings | | | | |
| S W | | | | Brakes | | | | |
| | 19/11 | | | Performance | V | | | |
| | | | S SC | Hand brake | · / | | | |
| S PT SC | 10 | | | Tyres (lowest observed tread | depth of tyres) | | | |
| <u> </u> | | | | Left front | 3.5 mm | | | |
| | | | S | Right front | | 3.0 mm | | |
| | | | | Left rear | | 3.5 mm | | |
| S | | SPT SD | S | Right rear | | 4.5 mn | | |
| | | | | Spare | Yes | | | |
| | and blemishes may not be on Comments | e displayed in the diagr | am | Suspension | 100 | | | |
| | | | | • | · / | | | |
| Stone chips in windscreen Rust around boot hinges Hole in boot | | | | Suspension performance | 1 | | | |
| | | | | Steering performance | - | | | |
| c 1111 b | | | Wet | Shock absorbers | | | | |
| | ring Body Inspection | | Air Conditioning / Heater | | Ī | | | |
| | e and Under Bonnet | t Inspection Comn | nents | Operation | / | <u> </u> | | |
| Rust on front st | ructure | | | Electrical / Accessories | | I | | |
| | | | | Head lights | | | | |
| | | | | Tail lights | / | | | |
| Interior Comn | | | | Indicators | / | | | |
| Seats: | Good | | | Dashboard warning lights | / | | <u> </u> | |
| Carpets: | Good | | | Wipers (front & rear) | | | | |
| Panels: | Good | | | Window winder FL | | | | |
| Dashboard: | Good | | | Window winder FR | | ļ | | |
| General Comr | ments | | Window winder RL | - | | | | |
| Right rear seath | pelt fray | | | Window winder RR | | | | |
| | | | | Rear view mirrors | | | | |
| | | | | Radio (basic test only) | / | | | |
| Road Condition | ns During Test Drive | Wet | | CD (basic test only) | | | 1 | |
| Engine Timing | Mechanism | Timing Chain | | Number of keys | 2 | | | |
| Evidence of Ca | m Belt Replacement | Yes | No Kms | Central locking | ~ | | | |
| Inspected by: | Samuel Weir | | | Remote locking | V | | | |
| 5 1 2 1 11 | D : D !! | | | 6 | | 1 | | |

I have read and understood this condition guide:

Inspection Date: 19 Nov 2025

Published by:

NAME

Desian Robb

SIGNATURE

Sat. nav. (basic test only)

Reversing camera