

•	Report ID:	27,797,318	Version:	2
	Created:	26 Nov 2025		

3	urner	S Bas	ic Condition Guide	Created: 26 Nov 2025	ve	ersion: 2		
						·		
Make:	Ford	Model:	Focus		ОК	Requires Attention	N/A	
Body Style:	Hatchback	Year:	2012	Engine				
Rego No.:	GQY726	Rego Expiry:	11 Sep 2026	Oil level	V			
WoF Expiry:	09 Dec 2025	Odometer:	156,475 Kms	Smoke & fumes				
Good No.:	27797318	VIN:	MPB1XXMXB1CY13769	Engine performance	V			
Next Service	: 127,850 Kms	Service History:	No	Noise	·			
	t is not a warranty	le for age and mileage. I	Coolant condition	/				
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.				Cooling performance	·			
				Radiator / Hoses (visual)	V			
ey = Scratch	R = Rust C = C	Crack *= Dec	als W = Significant scuffs	Transmission				
= Dent	PT = Paint defect P = P		one Chips	Operation	V			
	DT	60 60		Noise				
D	PT	SC SC	SP	Clutch			1	
				CV joints				
	TO ST			Wheel bearings	V			
sc	6/10			Brakes				
	119/			Performance	V			
			SC	Hand brake	V			
sc				Tyres (lowest observed tread	Tyres (lowest observed tread depth of tyres)			
				Left front		2	2.0 mm	
S SC P S P Note: some defects and blemishes may not be displayed in the diagram				Right front	2.5 mm			
				Left rear	6.5 mm			
				Right rear	2.5 mm			
				Spare	Yes			
Body Inspec	ction Comments			Suspension				
				Suspension performance	V			
				Steering performance		/		
				Shock absorbers	1			
Conditions D	Ouring Body Inspection		Dry	Air Conditioning / Heater		•		
Under Carriage and Under Bonnet Inspection Comments				Operation	V			
Minor engine	oil leak.		Electrical / Accessories					
				Head lights	V			
				Tail lights	V			
Interior Con	nments			Indicators	V			
Seats:	Average, RF seat height adjustment lever missing			Dashboard warning lights	V			
Carpets:	Good			Wipers (front & rear)	V			
Panels:				Window winder FL	1			
Dashboard: Good				Window winder FR	1			
General Cor	nments		Window winder RL	1				
	at 270,000 Kms.		Window winder RR	1				
	on outer edge.		Rear view mirrors	1				
Steering knoo	·N.			Radio (basic test only)	1			
		1_		•			-	

	Road Conditions During Test Drive		Dry		
	Engine Timing N	Mechanism	Cambelt	'	
Evidence of Cam Belt F		n Belt Replacement	✓ Yes	No	270,000 Kms
	Inspected by:	Caleb Spicer Lee			
	Published by:	Shanna Bullion			
	Inspection Date:	19 Nov 2025			

I have read and understood this condition guide:

NAME

SIGNATURE

1

1

•

CD (basic test only)

Sat. nav. (basic test only) Reversing camera

Number of keys

Central locking Remote locking