

Report ID:	27,797,450	Version:	3
Created:	26 Nov 2025		

Make:	Toyota	Model:	Hilux
Body Style:	Utility	Year:	2003
Rego No.:	BRT489	Rego Expiry:	11 Dec 2025
NoF Expiry:	08 Dec 2026	Odometer:	307,373 Kms
Good No.:	27797450	VIN:	JTFAK426000013040
Next Service:	317,374kms	Service History:	No
agnostic testing und	only. Consideration is made	een driven up to 50km/ł	arts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.
ey			
•	= Rust $C = C$		
= Dent PT	= Paint defect $P = Pi$	n dent SC = Stor	ne Chips
sc	S P	T P SC	
D (育 し し		
$ \beta$	BOTH		
14			
sc	IB SE		
P SC	D F	T SC	
		disclosed in the discour	
ote: some defects a Body Inspection	and blemishes may not be	displayed in the diagra	ım
zay mopeetic	30		
Conditions Duri	ing Body Inspection		Drv
	ng Body Inspection	Inspection Comm	Dry
	ng Body Inspection	Inspection Comm	
		Inspection Comm	
		Inspection Comm	
Under Carriage	e and Under Bonnet	Inspection Comm	
	e and Under Bonnet	Inspection Comm	
Under Carriago	e and Under Bonnet	Inspection Comm	

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	1		
Noise	\(\tau \)		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission		<u> </u>	
Operation	V		
Noise	/		
Clutch			1
CV joints			~
Wheel bearings	1		
Brakes		l	
Performance	/		
Hand brake	1		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			1.5 mm
Right front			1.5 mm
Left rear			5.5 mm
Right rear			5.5 mm
Spare	Yes		
Suspension			
Suspension performance	1		
Steering performance	1		
Shock absorbers	<i>'</i>		
Air Conditioning / Heater			
Operation Operation		Ι	V
Electrical / Accessories			
Head lights	V	1	
Tail lights	V		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL			
Window winder FR	<i>'</i>		
Window winder RL	_		
Window winder RR			
Rear view mirrors			
	J		
Radio (basic test only)	4		
CD (basic test only)	3	l	L
Number of keys Control locking		1	
Central locking			
Remote locking			
Sat. nav. (basic test only)			
Reversing camera		ļ	

Road Condition	s During Test Drive	Dry		
Engine Timing	Mechanism	Cambelt	,	
Evidence of Car	n Belt Replacement	✓ Yes	No	234,023 Kms
Inspected by: LukaAjitvan Woer		den		
Published by:	Harry Dodds			
Inspection Date:	19 Nov 2025			

have read and understood
this condition quide

Dashboard:

General Comments

Average

NAME			