

Basic Condition Guide

•	Report ID:	27,797,547	Version:	3
	Created:	02 Dec 2025		

mm mm mm mm

		Raci	c Condition Guide	11cport 10. 27,707,047	VC	131011.	
	nue		——————————————————————————————————————	Created: 02 Dec 2025	5		
Make:	Holden	Model:	Colorado			Requires	
Body Style:	Utility	Year:	2013	Engine	OK	Attention	N/
Rego No.:	HEB543	Rego Expiry:	20 Jun 2026	Oil level	· ·		1
WoF Expiry:	03 Jun 2026	Odometer:	140,072 Kms	Smoke & fumes	V		-
Good No.:	27797547	VIN:	MMU148FH0DH640039	Engine performance	· ·		-
Next Service:	due 131000	Service History:	Yes	Noise	V		
Note: This report is	not a warranty		,	Coolant condition	V		
diagnostic testing ur	ndertaken. The vehicle has b	een driven up to 50km/	arts have not been dismantled or h from cold. The Vendor recommends a	Cooling performance	· ·		
full mechanical insp	ection prior to purchase an	d this can be arranged f	or an additional charge.	Radiator / Hoses (visual)			
Key		5l # D	la W. Chaifean a ff	Transmission	-		
	= Rust $C = CT = Paint defect P = P$		ls W = Significant scuffs ne Chips	Operation	· ·		Τ
				Noise	· /		
S		SDSRP	SRPW	Clutch	· /		
				CV joints			<u>ا</u>
			SP	Wheel bearings	· ·		
SW 6				Brakes			
	19r 11			Performance	· ·		1
			S	Hand brake	V		
S SC				Tyres (lowest observed tread depth of tyres)			
				Left front			5.0 r
			SRPW	Right front			5.0 ı
	\angle			Left rear			8.0 ı
S D PT SC		SD SD	SRW	Right rear		;	3.0 ı
Note: some defects	and blemishes may not be	e displayed in the diagra	am	Spare	Yes		
Body Inspecti	on Comments			Suspension			
Headlights clou				Suspension performance	✓		
Large stone chi	ips in windscreen			Steering performance	/		
				Shock absorbers	/		
Conditions Du	ring Body Inspection		Dry	Air Conditioning / Heate	r		
Under Carriag	ge and Under Bonnet	Inspection Comn	nents	Operation	/		
				Electrical / Accessories			
				Head lights	/		
				Tail lights			
Interior Comn	nents			Indicators	/		
Seats:	Average			Dashboard warning lights			
Carpets:	Average			Wipers (front & rear)			
Panels:	Average			Window winder FL			<u> </u>
Dashboard:	Average			Window winder FR			<u> </u>
General Comr	ments			Window winder RL			

Road Condition	s During Test Drive	Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	✓ No	Kms
Inspected by:	Samuel Weir			
Published by:	Darren Beban			
Inspection Date:	20 Nov 2025			

SIGNATURE				
	SIGNATU	JRE		

1

2

1 1

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera