

1:4: . .

•	Report ID:	27,797,704	Version:	1
	Created:	19 Nov 2025		

		Poci	c Condition Guide	Report ID: 21
	nuel	S Dasi	C Condition Guide	Created: 19
Make:	Holden	Model:	Epica	-
Body Style:	Sedan	Year:	2011	
Rego No.:	BRADDI	Rego Expiry:	15 Dec 2025	Engine
WoF Expiry:	17 Nov 2026	Odometer:	98,705 Kms	Oil level
Good No.:	27797704	VIN:	KL3LA69LJBB089535	Smoke & fume
Next Service:	108,558 kms	Service History:	Yes	Engine perforr
	,	Service History.	100	Noise
	only. Consideration is made		arts have not been dismantled or	Coolant condit
	ndertaken. The vehicle has b ection prior to purchase an		n from cold. The Vendor recommends a or an additional charge.	Cooling perfor
Key		,		Radiator / Hose
•	= Rust $C=C$	rack *= Deca	ls W = Significant scuffs	Transmission
D = Dent P	T = Paint defect P = P	in dent SC = Stor	ne Chips	Operation
D PT		S P S	SP	Noise
DFI		3 3		Clutch
			S	CV joints
	Ma OF			Wheel bearing
s 6				Brakes
	19/			Performance
s sc			Hand brake	
S D SC	to the			Tyres (lowest o
3530 00				Left front
			(Q)	Right front
				Left rear
S D	W	SS	WP	Right rear
Note: some defects	and blemishes may not be	displayed in the diagra	um	Spare
	ion Comments	displayed in the diagra		Suspension
Stone chips in				Suspension pe
FR door lamp r				Steering perfo
Room lamp not	glowing			Shock absorbe
Conditions Du	ring Body Inspection		Wet	Air Condition
	ge and Under Bonnet	Inspection Comm		
Fwd	ge and Onder Bonnet	inspection comm	ients	Operation / A a
Engine oil leak				Electrical / Ac
				Head lights
1	<u> </u>			Tail lights
Interior Comn	I			Indicators
Seats:	Good			Dashboard wa
Carpets:	Good			Wipers (front &
Panels: Good				Window winde
Dashboard:	Good			Window winde
General Com	ments			Window winde
				Window winde

	OK	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise	V		
Coolant condition	V		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	/		
Clutch			~
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	✓		
Hand brake	~		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			7 mm
Right front			7 mm
Left rear			7 mm
Right rear			7 mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation		'	
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	V		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	>		
Radio (basic test only)	/		
CD (basic test only)	/		
Number of keys	2		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			
Reversing camera			V

Road Conditions During Test Drive		Wet	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by:	Vasanthakumar Mayilswamy		
Published by:	Vasanthakumar Mayilswamy		
Inspection Date:	19 Nov 2025		

have read and understood
this condition guide:

NAME	

SI	GN	IAT	UF	₹F