

Basic Condition Guide

Report ID:	27,797,817	Version:	1
Created:	24 Nov 2025		

Make:	Ford	Model:	Transit			Requires	1	
Body Style:	Minibus	Year:	2017		OK	Attention	N/A	
Rego No.:	KUB510	Rego Expiry:	27 Feb 2026	Engine			1	
WoF Expiry:	03 Mar 2026	Odometer:	190,453 Kms	Oil level	/			
Good No.:	27797817	VIN:	WF0HXXTTGHHP28926	Smoke & fumes	/			
Next Service:	213,618 kms	Service History:	No	Engine performance	/			
ote: This report is	· ·	Service History.	Noise	/				
•	only. Consideration is mad adertaken. The vehicle has b	de for age and mileage. F	Coolant condition	/				
l mechanical insp	ection prior to purchase ar	nd this can be arranged	Cooling performance	V				
еу			Radiator / Hoses (visual)	/				
		Crack *= Deca	Transmission					
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips				Operation	V			
		S		Noise	/			
$\overline{}$		\top		Clutch	V			
			SD	CV joints	V			
S D				Wheel bearings	/			
- A	18			Brakes	T .			
		$\parallel \parallel \parallel \perp \parallel$	R	Performance	/			
				Hand brake	/			
D R				Tyres (lowest observed tread depth of tyres)				
			sc	Left front			6 mm	
				Right front			6 mm	
	-		Left rear	4 mr				
		SDSD	Right rear	4 mn				
ote: some defects	and blemishes may not be	e displayed in the diagr	am	Spare	Yes			
Body Inspecti	on Comments		Suspension					
				Suspension performance	/			
				Steering performance	/			
			Dry	Shock absorbers	/			
	ring Body Inspection		Air Conditioning / Heater					
Under Carriag	e and Under Bonne	t Inspection Comn	Operation	/				
				Electrical / Accessories	_	Ţ	,	
				Head lights	/			
				Tail lights	/			
Interior Comm	nents		Indicators	/				
Seats:	Poor			Dashboard warning lights	/			
Carpets:	Average	Wipers (front & rear)	/					
Panels:	Average		Window winder FL	/				
Dashboard:	Average		Window winder FR	/				
General Comr	ments		Window winder RL			1		
	dicator lens broken, f	front bumper grill da	Window winder RR			~		
			المصاحب المصالح المصالين والمساورة					
ear reflector da	ımage, L sliding door	body seal torn, R r	ear window handle broken, L erbody rust,	Rear view mirrors	/			
ear reflector da		body seal torn, R r		Rear view mirrors Radio (basic test only)	V			
ear reflector da ear differential	ımage, L sliding door	body seal torn, R r			_			

I have read and understood this condition guide:

Inspection Date: 24 Nov 2025

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Marlon Espena

Marlon Espena

NAME

Yes

No

SIGNATURE

Kms

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

1

1