

Report ID:	27,798,324	Version:	2
Created:	21 Nov 2025		


Make:	Ford	Model:	Ranger
Body Style:	Utility	Year:	2019
Rego No.:	RLQ691	Rego Expiry:	
WoF Expiry:	06 Jul 2024	Odometer:	150,807 Kms
Good No.:	27798324	VIN:	MPBUMFE60JX195577
Next Service:	over due	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Windscreen stone chip cracked  
Bonnet opening latch needs refit  
FR door interior seal torn

Conditions During Body Inspection Dry

## Under Carriage and Under Bonnet Inspection Comments

4wd

## Interior Comments

Seats:	FR seat base trim cracked
Carpets:	Good
Panels:	FR , RL and RR door handle surround scratches
Dashboard:	Good

## General Comments

There is warning light on which is an orange spanner light which is equivalent to "Fault Warning". Further investigation is required to be accessed.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms
Inspected by:	Vasanthakumar Mayilswamy
Published by:	Ben Nicholson
Inspection Date:	21 Nov 2025

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			11.0 mm
Right front			11.0 mm
Left rear			11.0 mm
Right rear			11.0 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights		✓	
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)	✓		
Reversing camera	✓		

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_