


•	Report ID:	27,799,718	Version:	4
	Created:	29 Nov 2025		

Make:	Ssangyong	Model:	Korando
Body Style:	SUV	Year:	2013
Rego No.:	HDG820	Rego Expiry:	07 May 2026
WoF Expiry:	13 Dec 2026	Odometer:	132,305 Kms
Good No.:	27799718	VIN:	KPTB0A18SDP132952
Next Service:	142000 kms	Service History:	Yes

diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch* = DecalsW = Significant scuffs R = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Poor	
Dashboard:	Good	
General Comments		

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Eleoit Kumar	
Published by:	Sam Huang	
Inspection Date:	20 Nov 2025	

have read and understood		
his condition guide:	NAME	

	ОК	Requires Attention	N/A
Engine			
Oil level	1		
Smoke & fumes	~		
Engine performance	~		
Noise	~		
Coolant condition	\(\tau \)		
Cooling performance	~		
Radiator / Hoses (visual)	V		
Transmission			
Operation	~		
Noise	~		
Clutch			/
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	/		
Hand brake	~		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		8	3.0 mm
Right front		3	3.0 mm
Left rear		2	2.0 mm
Right rear		3	3.0 mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	V		
Dashboard warning lights	~		
Wipers (front & rear)	1		
Window winder FL	V		
Window winder FR	V		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)	1		
Number of keys	2		
Central locking	1		
Remote locking	1		
Sat. nav. (basic test only)			/
Reversing camera			1

SIGNATURE		