

Report ID: 27,799,760		27,799,760	Version:	2
	Created:	01 Dec 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	1		
Smoke & fumes	1		
Engine performance	/		
Noise	V		
Coolant condition	V		
Cooling performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	/		
Clutch			'
CV joints	/		
Wheel bearings	✓		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		7	7.0 mm
Right front		7	7.0 mm
Left rear		6	3.0 mm
Right rear		7	7.0 mm
Spare	Yes		
Suspension			
Suspension performance	•		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	V		
Window winder FL			
Window winder FR	/		
Window winder RL	/		
Window winder RR	•		
Rear view mirrors	•		
Radio (basic test only)	/		
CD (basic test only)			
Number of keys	2		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)	•		
Reversing camera	/		

Make:	Toyota	Model:	Rav4
Body Style:	SUV	Year:	2022
Rego No.:	PAP505	Rego Expiry:	15 Feb 2026
WoF Expiry:	15 Dec 2026	Odometer:	83,409 Kms
Good No.:	27799760	VIN:	JTMBW3FV40D562262
Next Service:	93,400km	Service History:	Yes
Note: This vanaut is not a wayyantu			

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

LF door exterior mirror indicator small crack.

Right front doorstep plate painted surface paint worn.

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Undertray torn.

Interior Comments	
Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good
General Comments	

4WD. Windscreen stone chip been repaired.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Sharnae Smith	
Published by:	Henry Manders	
Inspection Date:	25 Nov 2025	

I have read and understood
this condition guide:

NAME			