

•	Report ID:	27,800,959	Version:	3
	Created:	27 Nov 2025		

	umer	S Basi	c Condition Guide	Created: 27 Nov	2025		
Make:	Toyota	Model:	Rav4		,	Requires	
Body Style:	SUV	Year:	2021	-	OK	Attention	N/A
	NZA960	Rego Expiry:	14 Dec 2025	Engine			
	19 Nov 2026			Oil level	<i>\</i>		
	27800959		·	Smoke & fumes	<i>'</i>		
				Engine performance			
		Jet vice i iistory.		Noise	•		<u> </u>
•	•	e for age and mileage. Pa	arts have not been dismantled or	Coolant condition	•		<u> </u>
iagnostic testing un ull mechanical inspe	dertaken. The vehicle has be ection prior to purchase and	een driven up to 50km/f d this can be arranged f	or an additional charge.	Cooling performance	te 🗸		
(ey				Radiator / Hoses (vis	sual)		
-	= Rust $C = C$	rack *= Deca	ls W = Significant scuffs	Transmission		,	
D = Dent P1	Γ = Paint defect $P = Pi$	in dent SC = Stor	ne Chips	Operation	•		
		SC		Noise	· ·		
$\overline{}$				Clutch			'
			W	CV joints	✓		
				Wheel bearings	•		
Rego No.: NZA960 Rego Expiry: 14 Dec 2025 WoF Expiry: 19 Nov 2026 Odometer: 121,693 Kms Good No.: 27800959 VIN: JTMRW3FV10D13141* Next Service: 135,300km Service History: Yes Ste: This report is not a warranty is report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or agnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recomment Imechanical inspection prior to purchase and this can be arranged for an additional charge. Py Scratch R = Rust C = Crack *= Decals W = Significant s = Dent PT = Paint defect P = Pin dent SC = Stone Chips SC SC S SC SC S R S Seats: Good Interior Comments Interior Comments		Brakes					
				Performance	· ·		
			RSC	Hand brake	· ·		
SC	8			Tyres (lowest observ	ved tread depth of	tyres)	
				Left front		6	3.0 mm
			(Q)	Right front		6	6.0 mm
				Left rear		3	3.0 mm
				Right rear		3	3.0 mm
lote: some defects	and blemishes may not be	displayed in the diagra	ım	Spare	Yes		
				Suspension			
LF door interior	trim torn. Cargo interi	or boot area deck l	poard small dents.	Suspension perform	nance 🗸		
Windscreen sto	ne chip has been repa	aired.		Steering performan			
				Shock absorbers			
Conditions Dur	ing Body Inspection		Dry	Air Conditioning /	Heater		
		Inspection Comm	-	Operation	· ·		
				Electrical / Accesso			
				Head lights	· ·		
				Tail lights	· ·		
Interior Comm	nents			Indicators			
				Dashboard warning	-		
Carpets:	Good			Wipers (front & rear)	_		
Panels:	Good			Window winder FL			
Dashboard:	Good			Window winder FR	· /		
General Comn	iletits			Window winder RL	•	1	i

	-		
Dashboard:	Good		٧
General Comm	nents		٧
			٧
			F
			F
Road Condition	s During Test Drive	Dry	(
Engine Timing I	Mechanism	Timing Chain	1
Evidence of Car	n Belt Replacement	Yes No Kms	; (
Inspected by:	Sharnae Smith		F
Published by:	Henry Manders		9
Inspection Date:	25 Nov 2025		ı
		-	
I have read and u			
this condition gu	this condition guide: NAME		

SIGNATURE			

Right front		6.0 mm
Left rear		3.0 mm
Right rear		3.0 mm
Spare	Yes	
Suspension		
Suspension performance	V	
Steering performance	V	
Shock absorbers	/	
Air Conditioning / Heater		
Operation	✓	
Electrical / Accessories		
Head lights	V	
Tail lights	V	
Indicators	V	
Dashboard warning lights	V	
Wipers (front & rear)	V	
Window winder FL	V	
Window winder FR	V	
Window winder RL	V V V V V V V V V V V V V V V V V V V	
Window winder RR	V	
Rear view mirrors	V	
Radio (basic test only)	V	
CD (basic test only)		/
Number of keys	2	
Central locking	V	
Remote locking	V	
Sat. nav. (basic test only)	V	
Reversing camera	V	