Report ID:	27,801,065	Version:	1
Created:	20 Nov 2025		

Requires Attention

N/A

5 mm 5 mm 6 mm 6 mm

1

1

1

1

1

1

1 ĺ

1

1

1

1

1 1

Suspension performance

Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

Steering performance

Shock absorbers

Operation

Head lights

Tail lights

Indicators

OT			in Complition Code	Report ID:	27,801,065	Ve	rsion:
	urner	S Basi	c Condition Guide	Created:	20 Nov 2025		
Make:	Honda	Model:	Stream			ОК	Rec
Body Style:	Wagon	Year:	2008	Engine		<u> </u>	71000
Rego No.:	MBJ504	Rego Expiry:	18 Mar 2026	Oil level		·	
WoF Expiry:	23 Aug 2026	Odometer:	175,881 Kms	Smoke & fu	ımes	1	1
Good No.: 27801065 VIN:		VIN:	7AT08GADX19022833	Engine performance		1	
Next Service:	183000	Service History:	No	Noise	Torritance	1	
Note: This report is	•	,		Coolant co	ndition	1	
diagnostic testing u	ndertaken. The vehicle has b	een driven up to 50km/	arts have not been dismantled or h from cold. The Vendor recommends a	Cooling pe	rformance	1	
Radiator / Ho					Hoses (visual)	1	
Key $S = Scratch$ $R = Rust$ $C = Crack$ $* = Decals$ $W = Significant scuffs$				Transmission			
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips Operation Noise Clutch CV joints Wheel bearings Brakes						V	Π
						1	
						1	
					/		
					Brakes		
Performance						/	
				Hand brake	e	/	
					Tyres (lowest observed tread depth of tyres)		
		Left front					
			SD	Right front			
Left rear							
		s		Right rear			
Note: some defects and blemishes may not be displayed in the diagram				Spare		Yes	
Body Inspection Comments				Suspensio	n		

Damage on tailgate

I have read and understood this condition guide:

Conditions During Body Inspection		
Under Carriage and Under Bonnet Inspection Comments		

Interior Comm	Interior Comments	
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
General Comments		

Road Condition	s During Test Drive	Dry		
Engine Timing Mechanism		Timing Chain		
Evidence of Cam Belt Replacement		Yes No Kms		
Inspected by:	Kilipati Mae			
Published by:	Kilipati Mae			
Inspection Date:	20 Nov 2025			

AME	SIGNATURE