

Report ID:	27,801,083	Version:	1
Created:	25 Nov 2025		


Make:	Volkswagen	Model:	Polo
Body Style:	Hatchback	Year:	2007
Rego No.:	JZQ504	Rego Expiry:	25 Feb 2026
WoF Expiry:	26 Nov 2026	Odometer:	104,051 Kms
Good No.:	27801083	VIN:	WVWZZZ9NZ7D025249
Next Service:	114,050km's	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Plastic cover missing off front corner of right side roof rail. Plastic cover missing off rear window wiper arm. Indicator repeater lens in left side wing mirror is cracked, broken & wing mirror cover is cracked/broken. Radio aerial stork is missing. Scratches & scuffs on left side sill.

Conditions During Body Inspection Dry

## Under Carriage and Under Bonnet Inspection Comments

## Interior Comments

Seats:	Average
Carpets:	Good
Panels:	Good
Dashboard:	Average

## General Comments

Crack in left side of top dashboard panel. Cracks in left side of dashboard. Fabric worn on back rest of driver's seat.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms
Inspected by:	Jason Young
Published by:	Tiaan Pienaar
Inspection Date:	25 Nov 2025

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			6.0 mm
Right front			5.0 mm
Left rear			6.4 mm
Right rear			6.6 mm
Spare		N/A	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_