

•	Report ID:	27,801,229	Version:	2
	Created:	29 Nov 2025		

Basic Condition Guide			report ib:	27,001,229	Ve	ersion.		
	oniei			Created:	29 Nov 2025			
Make:	Mazda	Model:	CX-3				Require	
Body Style:	SUV	Year:	2020			OK	Attentio	on N/A
Rego No.:	NEQ122	Rego Expiry:	28 Feb 2026	Engine				
WoF Expiry:	13 Dec 2025	Odometer:	60,421 Kms	Oil level		V	-	_
Good No.:	27801229	VIN:	JM0DK2W7A01560158	Smoke & fu		/		-
Next Service:	67,000kms	Service History:	Yes	Engine per	formance	/		+
ote: This report i	,	Service History.		Noise		/		_
nis report is a guid	e only. Consideration is mad	le for age and mileage. P	arts have not been dismantled or	Coolant co	ndition	/		
	ındertaken. The vehicle has b pection prior to purchase an		h from cold. The Vendor recommends a for an additional charge.	Cooling pe	rformance	/		
ey				Radiator /	Hoses (visual)	/		
-	R = Rust $C = C$	Crack *= Deca	ls W = Significant scuffs	Transmiss	ion			
= Dent P	PT = Paint defect P = P	Pin dent SC = Sto	ne Chips	Operation		/		
		* S*		Noise		/		
				Clutch	Clutch			/
				CV joints	CV joints 🗸			
	MA UN			Wheel bearings 🗸				
SDC				Brakes				
	1191			Performan	ce	1		\Box
PT					e	1		
					Tyres (lowest observed tread depth of tyres)			
							6.0 m	
					Right front			6.0 m
* S* DS				Left rear			5.5 m	
				Right rear				5.5 m
Note: some defects and blemishes may not be displayed in the diagram				Spare Yes				
	ion Comments	e displayed in the diagn	um	Suspensio	on .			
- · · / · · · · ·				•	n performance	V	Τ	Т
					erformance	1		
				Shock abso		1		+
Conditions During Body Inspection Dry				ioning / Heater				
Under Carriage and Under Bonnet Inspection Comments			Operation 🗸					
onder Carriage and Onder Bonnet Inspection Comments				Electrical / Accessories				
				Head light		V		T
				Tail lights		1	 	+
Interior Comments				Indicators		1	 	+
Seats:	Good				I warning lights	V	 	+
	Good			Dashboard warning ligh		V		_
Carpets:				Wipers (front & rear) Window winder FL		+		
Panels: Good					· ·	-	+	
Dashboard: Good			Window w		<i>V</i>	-	_	
General Com	ments			Window w	inaer KL	/		\dashv

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Timing Ch	ain	
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Marlon Espena			
Published by:	Henry Manders			
Inspection Date:	25 Nov 2025			

One remote key not working, driver body seal torn, front bumper damage, parcel tray

I have read and understood this condition guide:

missing one cord string.

NAME			

IGNATURE		

1

V

2

1

1

1

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)