

•	Report ID:	27,801,553	Version:	1
	Created:	21 Nov 2025		

	ОК	Requires Attention	N/A
Engine		7101011	
Oil level	1		
Smoke & fumes	1		
Engine performance	V		
Noise	1		
Coolant condition	1		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission		1	
Operation	1		
Noise	/		
Clutch			1
CV joints	~		
Wheel bearings	1		
Brakes			
Performance	1		
Hand brake	1	1	
Tyres (lowest observed tread d	epth of	tyres)	
Left front			7 mm
Right front		3	3.5 mm
Left rear		7	7.5 mm
Right rear			5.5 mm
Spare	Yes		
Suspension			
Suspension performance	1		
Steering performance	~		
Shock absorbers	1		
Air Conditioning / Heater			
Operation		/	
Electrical / Accessories			
Head lights	/		
Tail lights	~		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL		V	
Window winder FR	1		
Window winder RL			
Window winder RR			
Williad Williad Till	V		
Rear view mirrors	V		
Rear view mirrors	V		
Rear view mirrors Radio (basic test only)	\(\times \)		
Rear view mirrors Radio (basic test only) CD (basic test only)	\(\times \) \(\t		
Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	\(\tau \)		
Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	\(\tau \)		


Make:	Ford	Model:	Focus
Body Style:	Hatchback	Year:	2014
Rego No.:	HMH998	Rego Expiry:	14 Dec 2025
WoF Expiry:	26 Nov 2026	Odometer:	226,294 Kms
Good No.:	27801553	VIN:	MPB1XXMXB1EJ68049
Next Service:	235000	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Small holes in driver seat and right rear passenger seatt

Conditions During Body Inspection	Wet			
Under Carriage and Under Bonnet Inspection Comments				

Interior Comments			
Seats:	Average		
Carpets:	Good		
Panels:	Good		
Dashboard:	Good		
	_		

General Comments

Air Con not cold

		T
Road Conditions During Test Drive		Wet
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Kris Milne	
Published by:	Kris Milne	
Inspection Date:	21 Nov 2025	

have read and understood
his condition quide

NAME			

SI	GN	IA.	TU	RF