

## Basic Condition Guide

•	Report ID:	27,801,802	Version:	1
	Created:	20 Nov 2025		

7	ntue	<b>S</b> Basi	c Condition Guide	Created: 20 Nov 2025		131011.	
Make:	Holden	Model:	Trailblazer			Requires	
	SUV	Year:	2018	_		Attention	N/A
Body Style:	RLT594		22 Jan 2026	Engine			
Rego No.:	111111111	Rego Expiry:	22 Jan 2020	Oil level	/		
WoF Expiry:	20 Mar 2026	Odometer:	MMI MEGDICO ILIGAEGAA	Smoke & fumes	-		
Good No.:	27801802	VIN:	MMU156PK0JH645644	Engine performance	<b>/</b>		
Next Service:	178,200	Service History:	No	Noise	V		
ote: This report i	·	de for age and mileage. P	arts have not been dismantled or	Coolant condition	/		
iagnostic testing u ıll mechanical inst	ndertaken. The vehicle has pection prior to purchase a	been driven up to 50km/ nd this can be arranged f	arts have not been dismantled or h from cold. The Vendor recommends a or an additional charge.	Cooling performance	/		
(ey	, , , , , , , , , , , , , , , , , , , ,			Radiator / Hoses (visual)	V		
•	R = Rust C = 0	Crack *= Deca	ls W = Significant scuffs	Transmission			
	PT = Paint defect P = I		ne Chips	Operation	V		
S PT SC		D SC S PT SC	SPT	Noise	1		
3 PT 3C		5 P 1 SC	371	Clutch			1
			S	CV joints			~
	TO VI			Wheel bearings	V		
SP				Brakes			
	1191		S SC	Performance	V		
			Hand brake	1			
S D * SC	HA			Tyres (lowest observed tread depth of tyres)			
37 33				Left front	9.5 mm		
			Right front	9.5 m		 9.5 mr	
			Left rear	9.5		9.5 mi	
S PT SC S PT S PT			SPT	Right rear			9.5 mr
Note: some defects and blemishes may not be displayed in the diagram				Spare	Yes		
	ion Comments	e displayed in the diagre		Suspension			
Stone Chips W				Suspension performance	V		
Condensation	•			Steering performance	1		
Boot Tint Bubb	oling			Shock absorbers	1		
Conditions During Body Inspection Dry			Air Conditioning / Heater				
Under Carriage and Under Bonnet Inspection Comments				Operation	V		
				Electrical / Accessories			
				Head lights	1		
				Tail lights	<b>V</b>		<del>                                     </del>
Interior Com	ments			Indicators	1	+	<del>                                     </del>
Seats: Drivers Seat Torn			Dashboard warning lights		1	<del>                                     </del>	
Carpets:			Wipers (front & rear)		1	<del>                                     </del>	
Panels:	Average  LF Panel Damaged, LR Not Fitted Correctly		Window winder FL				
Dashboard:				Window winder FR			
Dashboard: Average  General Comments			Window winder RL				
General Com	IIIEIILS		willdow willder KL			<del> </del>	

Road Condition	s During Test Drive	Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	<b>V</b> No	Kms
Inspected by:	Samuel Weir			
Published by:	Samuel Weir			
Inspection Date:	20 Nov 2025			

I have read and understood this condition guide:

NAME			

SIGNATURE		

1

2

1

1

1

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera