


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | KIA         | Model:           | Sportage          |
| Body Style:   | SUV         | Year:            | 2022              |
| Rego No.:     | PAC55       | Rego Expiry:     | 27 Jan 2026       |
| WoF Expiry:   | 25 Dec 2026 | Odometer:        | 109,940 Kms       |
| Good No.:     | 27801856    | VIN:             | KNAPU81CSN7019538 |
| Next Service: | 122,000kms  | Service History: | Yes               |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

|                                   |     |
|-----------------------------------|-----|
| Conditions During Body Inspection | Dry |
|-----------------------------------|-----|

**Under Carriage and Under Bonnet Inspection Comments**
**Interior Comments**

|            |      |
|------------|------|
| Seats:     | Good |
| Carpets:   | Good |
| Panels:    | Good |
| Dashboard: | Good |

**General Comments**

Windscreen stone chip.

|                                   |  |
|-----------------------------------|--|
| Road Conditions During Test Drive | Dry  |
| Engine Timing Mechanism           | Timing Chain   |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes <input type="checkbox"/> No |
| Inspected by:                     | Marlon Espena  |
| Published by:                     | Henry Manders  |
| Inspection Date:                  | 26 Nov 2025  |

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 27,801,856  | Version: | 3 |
| Created:   | 23 Jan 2026 |          |   |

|   | OK  | Requires Attention | N/A |
|---|-----|--------------------|-----|
| <b>Engine</b>                                       |     |                    |     |
| Oil level   | ✓   |                    |     |
| Smoke & fumes                                       | ✓   |                    |     |
| Engine performance                                  | ✓   |                    |     |
| Noise   | ✓   |                    |     |
| Coolant condition                                   | ✓   |                    |     |
| Cooling performance                                 | ✓   |                    |     |
| Radiator / Hoses (visual)                           | ✓   |                    |     |
| <b>Transmission</b>                                 |     |                    |     |
| Operation   | ✓   |                    |     |
| Noise   | ✓   |                    |     |
| Clutch  |     |                    | ✓   |
| CV joints   | ✓   |                    |     |
| Wheel bearings                                      | ✓   |                    |     |
| <b>Brakes</b>                                       |     |                    |     |
| Performance   | ✓   |                    |     |
| Hand brake  | ✓   |                    |     |
| <b>Tyres (lowest observed tread depth of tyres)</b> |     |                    |     |
| Left front  | 5.0 | mm                 |     |
| Right front   | 5.0 | mm                 |     |
| Left rear   | 6.0 | mm                 |     |
| Right rear  | 6.0 | mm                 |     |
| Spare   | Yes |                    |     |
| <b>Suspension</b>                                   |     |                    |     |
| Suspension performance                              | ✓   |                    |     |
| Steering performance                                | ✓   |                    |     |
| Shock absorbers                                     | ✓   |                    |     |
| <b>Air Conditioning / Heater</b>                    |     |                    |     |
| Operation   | ✓   |                    |     |
| <b>Electrical / Accessories</b>                     |     |                    |     |
| Head lights   | ✓   |                    |     |
| Tail lights   | ✓   |                    |     |
| Indicators  | ✓   |                    |     |
| Dashboard warning lights                            | ✓   |                    |     |
| Wipers (front & rear)                               | ✓   |                    |     |
| Window winder FL                                    | ✓   |                    |     |
| Window winder FR                                    | ✓   |                    |     |
| Window winder RL                                    | ✓   |                    |     |
| Window winder RR                                    | ✓   |                    |     |
| Rear view mirrors                                   | ✓   |                    |     |
| Radio (basic test only)                             | ✓   |                    |     |
| CD (basic test only)                                | ✓   |                    |     |
| Number of keys                                      | 2   |                    |     |
| Central locking                                     | ✓   |                    |     |
| Remote locking                                      | ✓   |                    |     |
| Sat. nav. (basic test only)                         | ✓   |                    |     |
| Reversing camera                                    | ✓   |                    |     |

SIGNATURE \_\_\_\_\_