

| Report ID: | 27,802,040 | Version: | 1 |
|------------|-------------|----------|---|
| Created: | 28 Nov 2025 | | |


| Make: | Hyundai | Model: | Santa FE |
|---------------|-------------|------------------|-------------------|
| Body Style: | SUV | Year: | 2014 |
| Rego No.: | HLY128 | Rego Expiry: | 28 Feb 2026 |
| WoF Expiry: | 20 Oct 2026 | Odometer: | 213,530 Kms |
| Good No.: | 27802040 | VIN: | KMHSU81XSEU310651 |
| Next Service: | 223533 | Service History: | No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

| 1/ | |
|----|------------|
| n | ωv |

| rey | | | | |
|-------------|-------------------|--------------|------------------|------------------------|
| S = Scratch | R = Rust | C = Crack | * = Decals | W = Significant scuffs |
| D = Dent | PT = Paint defect | P = Pin dent | SC = Stone Chips | |



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Minor Stonechips on windscreen

| Conditions During Body Inspection | Dry |
|---|-----|
| Under Carriage and Under Bonnet Inspection Comments | |

All wheel drive

| Interior Comments | | |
|-------------------|------|--|
| Seats: | Good | |
| Carpets: | Good | |
| Panels: | Good | |
| Dashboard: | Good | |
| Conoral Comments | | |

A/C not cold

| Road Conditions During Test Drive | | Dry | |
|-----------------------------------|------------------|--------------|--|
| Engine Timing Mechanism | | Timing Chain | |
| Evidence of Cam Belt Replacement | | Yes No Kms | |
| Inspected by: | Cameron Senior-A | Arnold | |
| Published by: | Janine Bell | | |
| Inspection Date: | 22 Nov 2025 | | |

| I have read and understood |
|----------------------------|
| this condition guida |

| NAME | | | |
|------|--|--|--|

SIGNATURE

| | ОК | Requires Attention | N/A |
|--------------------------------|-------------|-----------------------|----------|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | / | | |
| Engine performance | / | | |
| Noise | / | | |
| Coolant condition | \(\tau \) | | |
| Cooling performance | / | | |
| Radiator / Hoses (visual) | / | | |
| Transmission | | | |
| Operation | > | | |
| Noise | > | | |
| Clutch | | | / |
| CV joints | > | | |
| Wheel bearings | / | | |
| Brakes | | | |
| Performance | / | | |
| Hand brake | / | | |
| Tyres (lowest observed tread d | epth of | tyres) | |
| Left front | | 2 | 2.8 mm |
| Right front | | 2 | 2.3 mm |
| Left rear | | 2 | 2.6 mm |
| Right rear | | 2 | 2.7 mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | / | | |
| Steering performance | / | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | | ✓ | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | / | | |
| Indicators | V | | |
| Dashboard warning lights | | | |
| Wipers (front & rear) | / | | |
| Window winder FL | / | | |
| Window winder FR | V | | |
| Window winder RL | / | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | / | | |
| CD (basic test only) | | | V |
| Number of keys | 1 | | |
| Central locking | ✓ | | |
| Remote locking | / | | |
| Sat. nav. (basic test only) | / | | |
| Reversing camera | V | | |
| | | | |