

•	Report ID:	27,802,399	Version:	2
	Created:	29 Nov 2025		


	ОК	Requires Attention	N/A
Engine			_
Oil level	~		
Smoke & fumes	1		
Engine performance	~		
Noise	~		
Coolant condition	~		
Cooling performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	/		
Noise	/		
Clutch			/
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			7 mm
Right front			7 mm
Left rear			5.0 mm
Right rear			5.0 mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories	r	Y	
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	•		
Window winder FR	~		
Window winder RL	•		
Window winder RR	•		
Rear view mirrors	•		
Radio (basic test only)	/		
CD (basic test only)	•		<u> </u>
Number of keys	1		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			
Reversing camera			

Make:	Mazda	Model:	CX-9
Body Style:	suv	Year:	2015
Rego No.:	JGQ978	Rego Expiry:	20 Aug 2026
WoF Expiry:	12 Dec 2026	Odometer:	128,344 Kms
Good No.:	27802399	VIN:	JM0TB10A5F0432470
Next Service:	138000kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key * = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Spider rust on roof

Conditions During Body Inspection		Dry	
Under Carriage and Under Bonnet Inspection Comments			

Underbody surface rust Engine oil seepage

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
General Comments		

Wheel alignment not straight

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Sione Mae	
Published by:	Neil Honeyman	
Inspection Date:	21 Nov 2025	

I have read and understood
this condition guide

NAME			