

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



No Spare Tyre - Tools Available

Oil Leak
Underbody Cover Split

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Good

Coolant Low

I have read and understood
this condition guide:

	OK	Requires Attention	N/A
--	----	-----------------------	-----

Spare	No
-------	----

Reversing camera	✓		
------------------	---	--	--