

Report ID:	27,802,692	Version:	1
Created:	21 Nov 2025		

Лake:	Volkswagen	Model:	Touareg
Body Style:	SUV	Year:	2013
Rego No.:	KWU432	Rego Expiry:	09 Dec 2025
WoF Expiry:	03 Sep 2026	Odometer:	225,621 Kms
Good No.:	27802692	VIN:	WVGZZZ7PZED017657
Next Service:	238000kms	Service History:	No
diagnostic testing ur	only. Consideration is mad	oeen driven up to 50km/	arts have not been dismantled or h from cold. The Vendor recommends a for an additional charge.
Key			
	= Rust $C = C$ T = Paint defect $P = F$	Crack $* = Deca$ Fin dent $SC = Sto$	W = Significant scuffs ne Chips
		SP SP	WSPT
$\overline{}$		\top	
			S
SW (
-	18		
1			P SC
SC			
			SP
	W	S	WSP
) (
	and blemishes may not be	e displayed in the diagra	am
	and blemishes may not be	e displayed in the diagra	am
		e displayed in the diagra	am
		e displayed in the diagra	am
Body Inspecti	on Comments	e displayed in the diagra	
Body Inspection Conditions Du	ring Body Inspection		Dry
Conditions Du Under Carriage	ring Body Inspection		Dry
Body Inspection Conditions Du	ring Body Inspection		Dry
Conditions Du Under Carriage	ring Body Inspection		Dry
Conditions Du Under Carriag Minor Engine C	ring Body Inspection ge and Under Bonner		Dry
Conditions Du Under Carriage	ring Body Inspection ge and Under Bonner bil leak		Dry
Conditions Du Under Carriag Minor Engine C Interior Comm	ring Body Inspection ge and Under Bonner bil leak nents Average		Dry
Conditions Du Under Carriag Minor Engine C	ring Body Inspection ge and Under Bonner bil leak nents Average Average		Dry
Conditions Du Under Carriag Minor Engine C Interior Comm Seats: Carpets:	ring Body Inspection ge and Under Bonner bil leak nents Average Average Average		Dry
Conditions Du Under Carriag Minor Engine Co Interior Comm Seats: Carpets: Panels: Dashboard:	ring Body Inspection ge and Under Bonner bil leak nents Average Average Average Average Average		Dry
Conditions Du Under Carriag Minor Engine Co Interior Comm Seats: Carpets: Panels:	ring Body Inspection ge and Under Bonner bil leak nents Average Average Average Average Average		Dry
Conditions Du Under Carriag Minor Engine Co Interior Comm Seats: Carpets: Panels: Dashboard: General Comm	ring Body Inspection ge and Under Bonner bil leak nents Average Average Average Average Average		Dry

	ОК	Requires Attention	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Engine performance	\(\tau \)		
Noise	1		
Coolant condition	1		
Cooling performance	/		
Radiator / Hoses (visual)	1		
Transmission			
Operation	1		
Noise	1		
Clutch			~
CV joints	1		
Wheel bearings	~		
Brakes			
Performance	1		
Hand brake	1		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			1.5 mm
Right front			1.5 mm
Left rear		3	3.5 mm
Right rear			1.0 mm
Spare	Yes		
Suspension			
Suspension performance	1		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	1		
Electrical / Accessories			
Head lights	1		
Tail lights	/		
Indicators	1		
Dashboard warning lights	•		
Wipers (front & rear)	/		
Window winder FL	1		
Window winder FR	/		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)	-		
Number of keys	2	I	<u> </u>
Central locking	- -	1	
Remote locking	<i>'</i>		
Sat. nav. (basic test only)	· /		
Reversing camera	<i>-</i>		
neversing carriera		<u> </u>	<u> </u>

I have read and understood this condition guide:

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Inspection Date: 21 Nov 2025

Lindsay Malpas

Jason Bucksey

Engine Timing Mechanism

Inspected by:

Published by:

N	Δ	M	E

Dry Unknown

Yes

No

SIGNATURE

Kms