

| Report ID: | 27,803,270 | Version: | 1 |
|------------|-------------|----------|---|
| Created: | 21 Nov 2025 | | |

| UTI | nuer | S Basi | c Condition Guide | Crea |
|------------------------|-----------------------------|-------------------------|--|-------|
| Make: | Hyundai | Model: | loniq | |
| Body Style: | Hatchback | Year: | 2022 | - |
| Rego No.: | RCS267 | Rego Expiry: | 08 Mar 2026 | Eng |
| WoF Expiry: | 14 Oct 2026 | Odometer: | 26,275 Kms | Oil I |
| Good No.: | 27803270 | VIN: | KMHC651DVNU290417 | Smo |
| Next Service: | 36000 | Service History: | Yes | Eng |
| diagnostic testing und | only. Consideration is made | een driven up to 50km/h | arts have not been dismantled or n from cold. The Vendor recommends a or an additional charge. | Coo |
| Key | | | | Rad |
| | = Rust $C = C$ | | 3 | Trai |
| D = Dent PT | = Paint defect $P = Pi$ | n dent SC = Stoi | ne Chips | Оре |
| | | P | | Nois |
| | | | | Clut |
| | \sim | | PW | CVj |
| | | <u> </u> | | Whe |
| $ \beta$ | B T | | HIV | Bra |
| 111 | | | | Perf |
| | | | | Han |
| sc | | \longrightarrow | | Left |
| | | | | Righ |
| | | | | Left |
| | W | S P | WSP | Righ |
| Note: some defects a | and blemishes may not be | displayed in the diagra | m | Spa |
| Body Inspection | | displayed in the diagra | | Sus |
| , , | | | | Sus |
| | | | | Stee |
| | | | | Sho |
| Conditions Duri | ng Body Inspection | | Dry | Air |
| | e and Under Bonnet | Inspection Comm | - | Оре |
| | | | | Elec |
| | | | | Hea |
| | | | | Tail |
| Interior Comm | ents | | | Indi |
| Seats: | Good | | | Das |

| | OK | Requires Attention | |
|--------------------------------|----------|-----------------------|-------------|
| Engine | OK | Attention | 11/74 |
| Oil level | · | <u> </u> | |
| Smoke & fumes | 1 | | |
| Engine performance | 1 | | |
| Noise | 1 | | |
| Coolant condition | 1 | | |
| Cooling performance | 1 | | |
| Radiator / Hoses (visual) | 1 | | |
| Transmission | • | | |
| Operation | · | 1 | |
| Noise | 1 | | |
| Clutch | | | |
| CV joints | 1 | | _ |
| Wheel bearings | 1 | | |
| Brakes | | | |
| Performance | V | l | |
| Hand brake | 1 | | |
| Tyres (lowest observed tread d | lenth of | turas) | |
| Left front | eptiroi | | 6 mm |
| Right front | | | 5 mm |
| Left rear | | | 4 mm |
| Right rear | | | 4 mm |
| Spare | N/A | | |
| Suspension | 14// | | |
| Suspension performance | / | | |
| Steering performance | V | | |
| Shock absorbers | <i>-</i> | | |
| Air Conditioning / Heater | | | |
| Operation | · | | |
| Electrical / Accessories | | | |
| Head lights | · | | |
| Tail lights | 1 | | |
| Indicators | 1 | | |
| Dashboard warning lights | 1 | | |
| Wipers (front & rear) | 1 | | |
| Window winder FL | 1 | | |
| Window winder FR | 1 | | |
| Window winder RL | 1 | | |
| Window winder RR | 1 | | |
| Rear view mirrors | 1 | | |
| Radio (basic test only) | 1 | | |
| CD (basic test only) | · / | | |
| Number of keys | 2 | <u> </u> | Ь |
| Central locking | - - | 1 | |
| Remote locking | <i>J</i> | | |
| Sat. nav. (basic test only) | | | |
| Reversing camera | 1 | | _ |
| neversing camera | | <u> </u> | |

| Road Conditions During Test Drive | | Dry | | |
|-----------------------------------|-------------|--------------|----|-----|
| Engine Timing Mechanism | | Timing Chain | I | |
| Evidence of Cam Belt Replacement | | Yes | No | Kms |
| Inspected by: | Sione Mae | | | |
| Published by: | Sione Mae | | | |
| Inspection Date: | 21 Nov 2025 | | | |

| have read and understood |
|--------------------------|
| his condition quide |

Carpets:

Panels:

Dashboard:

General Comments

Good

Good

Good

| NAME | | | |
|------|--|--|--|
| | | | |