

## **Basic Condition Guide**

•	Report ID:	27,803,939	Version:	1
	Created:	27 Nov 2025		

	ntuei	S Bas	Created: 27 Nov 2025					
Make:	Hyundai	Model:	Sonata		01/	Requires	N1/A	
Body Style:	Sedan	Year:	2005	Engine	OK	Attention	N/A	
Rego No.:	CSZ932	Rego Expiry:	30 Jun 2026		V			
WoF Expiry:	22 Jul 2026	Odometer:	147,344 Kms	Oil level Smoke & fumes	V			
Good No.:	27803939	VIN:	KMHEU41FR5A071092		1			
Next Service:	155,550km's	Service History:	No	Engine performance	V			
ote: This report is	not a warranty		Noise Coolant condition	1				
nis report is a guide	only. Consideration is mac ndertaken. The vehicle has l	de for age and mileage. F been driven up to 50km/		V				
ll mechanical insp	ection prior to purchase ar	nd this can be arranged	for an additional charge.	Cooling performance  Radiator / Hoses (visual)	V		1	
ey			Transmission					
		Crack *= Deca		V	<u> </u>			
= Dent P	T = Paint defect P = F	an dent SC = Sto	one Chips	Operation	1			
	S	SPSDPW	RSDP	Noise				
				Clutch				
	$\sim$		SPT	CV joints	<i>V</i>		-	
S SC				Wheel bearings	/			
$\neg \neg \rho$	18			Brakes		<u> </u>		
1		$\parallel \parallel \parallel \perp$	S R SC	Performance	<b>/</b>		-	
				Hand brake	<b>/</b>			
SC				Tyres (lowest observed tread depth of tyres)				
			Left front	6.0 mm				
			SR	Right front		6	5.0 mr	
			Left rear	6.2 mm				
SC [	S	s	Right rear	6.2 mm				
ote: some defects	and blemishes may not b	e displayed in the diagr	am	Spare	Yes			
	on Comments			Suspension				
			ng sensors is broken. Left front	Suspension performance	/			
yre rubber is si	tarting to show signs	or perisning.		Steering performance	V			
				Shock absorbers	<b>/</b>			
Conditions Du	ring Body Inspection		Air Conditioning / Heater					
<b>Under Carriag</b>	e and Under Bonne	t Inspection Comn	nents	Operation	<b>/</b>			
				Electrical / Accessories	_			
				Head lights		<b>V</b>		
				Tail lights	<b>/</b>			
Interior Comn	nents			Indicators	<b>V</b>			
Seats: Average				Dashboard warning lights	/			
Carpets:	Good			Wipers (front & rear)	~			
Panels:	Average	Window winder FL	~					
Dashboard:	Average		Window winder FR	~				
General Comr	ments		Window winder RL	1				
-	-	n low beam. A/C is	not getting cold. Rear parking	Window winder RR	1			
ensors are fau	Ity.			Rear view mirrors	1			
				Radio (basic test only)	1			
Road Condition	ns During Test Drive	Dry		CD (basic test only)	1			
		Timing Chain		Number of keys	2		1	
- J		H						

I have read and understood this condition guide:

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 24 Nov 2025

Jason Young

Henry Belt

NAME

Yes

No

SIGNATURE

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Kms

1