

Basic Condition Guide

•	Report ID:	27,804,071	Version:	1	
	Created:	02 Dec 2025			

	nue	S Bas	ic Condition Guide	Created: 02 Dec 2025				
Make:	Hyundai	Model:	140		01/	Requires		
Body Style:	Sedan	Year:	2013	Engine	OK	Attention	N/A	
Rego No.:	GZB544	Rego Expiry:	28 Oct 2026	Engine Oil level	V			
WoF Expiry:	05 Nov 2025	Odometer:	188,195 Kms		V			
Good No.:	27804071	VIN:	KMHLC41UMDU029042	Smoke & fumes	1	<u> </u>		
Next Service:		Service History:	No	Engine performance	1			
Note: This report is	not a warranty		Noise Coolant condition	1				
his report is a guide	e only. Consideration is mad ndertaken. The vehicle has b	e for age and mileage. F		1				
ull mechanical insp	ection prior to purchase an	nd this can be arranged	for an additional charge.	Cooling performance	V			
Кеу				Radiator / Hoses (visual)				
		Crack * = Deca		Transmission Operation				
D = Dent P	T = Paint defect P = P	Pin dent SC = Sto	Operation	-				
		S SC S R SC	Noise	/		1		
				Clutch				
	(0)		S SC	CV joints	-			
S PT SC				Wheel bearings	/			
- P				Brakes				
			S R SC	Performance		/		
				Hand brake	/			
S D SC				Tyres (lowest observed tread depth of tyres) Left front 7.0 mm				
			S PT SC	Left front				
				Right front	7.0 mm			
		S SC S SC		Left rear	7.0 mm			
				Right rear	7.0 mm			
	and blemishes may not be	e displayed in the diagr	am	Spare	Yes			
<u> </u>	ion Comments	ua atana ahin in fra	nt coroon	Suspension				
Paint faded in s	several places. Bullse	ye stone cnip in fro	nt screen	Suspension performance	-			
				Steering performance	-			
			_	Shock absorbers	/			
	ring Body Inspection		Dry	Air Conditioning / Heater		<u> </u>		
	ge and Under Bonnet		Operation	/				
Front and rear I up	brake pads needed fo	r WOF. Oil leaks. (Electrical / Accessories		<u> </u>			
				Head lights	/			
				Tail lights	/			
Interior Comr			Indicators	/				
Seats:	Average			Dashboard warning lights	/			
Carpets:	Average			Wipers (front & rear)	/			
Panels:	Average		Window winder FL	/				
Dashboard:	Average		Window winder FR	/				
General Com			Window winder RL	/				
Rhf interior han	idle broken. Reverse o	camera cloudy.		Window winder RR	/			
				Rear view mirrors	/			
				Radio (basic test only)	/			
Road Conditio	ns During Test Drive	Dry		CD (basic test only)	/			
		the second second						

I have read and understood this condition guide:

Inspection Date: 24 Nov 2025

Engine Timing Mechanism

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Gary Adams

Saxon Ewen

NAME

Timing Chain

No

Yes

SIGNATURE

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Kms

1

1

1