

Basic Condition Guide

Report ID: 27,804,783		Version:	3
Created:	26 Nov 2025		

	I		I	
Make:	Mitsubishi	Model:	Triton	
Body Style:	Utility	Year:	2021	
Rego No.: NGT506		Rego Expiry:	26 Jan 2026	
WoF Expiry:	25 Jan 2026	Odometer:	186,220 Kms	
Good No.:	27804783	VIN:	MMAJLKK10MH005083	
Next Service:	195,000 kms	Service History:	Yes	
diagnostic testing un	only. Consideration is made	een driven up to 50km/ł	arts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.	
Key				
	= Rust C = C		3	
D = Dent P	$\Gamma = Paint defect P = Pi$	in dent SC = Stor	ne Chips	
		* *	*	
	(O)=		(O) SD	
		· - '		
$ \beta$	ID/		THE PART OF THE PA	
7				
			D*	
		* *	D*	
	and blemishes may not be	displayed in the diagra	m	
Body Inspecti	on Comments			
			I_	
	ring Body Inspection		Dry	
Under Carriag	e and Under Bonnet	Inspection Comm	ents	
Interior Comm	1			
Seats:	Average			
Carpets:	Average			
Panels:	Average			
Dashboard:	Good			
General Comr	nents			
Tail lights crack	, rear top deck cover t	orn,		
Road Condition	ns During Test Drive	Dry		

	ОК	Requires Attention	
Engine	<u> </u>		,
Oil level	/		
Smoke & fumes	/		
Engine performance	✓		
Noise	/		
Coolant condition	~		
Cooling performance	V V		
Radiator / Hoses (visual)			
Transmission		<u> </u>	
Operation			
Noise	· /		
Clutch			
CV joints			
Wheel bearings			
Brakes			
Performance			
Hand brake			
Tyres (lowest observed tread de	enth of	tures)	
Left front	еритог		7 mm
Right front			7 mm
Left rear			7 mm
Right rear			7 mm
Spare	Yes		
Suspension	163		
Suspension performance	./	l	
Steering performance			
Shock absorbers	-1		
Air Conditioning / Heater	./	Ι	
Operation			
Electrical / Accessories		1	Γ
Head lights	<i>V</i>		
Tail lights			
Indicators	V		
Dashboard warning lights			
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL			
Window winder RR			
Rear view mirrors			
Radio (basic test only)			
CD (basic test only)			
Number of keys	2	1	
Central locking	/		
Remote locking	✓		
		I	<i> </i>
Sat. nav. (basic test only)			<u> </u>

Inspection Date:	26 Nov 2025
I have read and u this condition gu	

Engine Timing Mechanism

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Marlon Espena

Marlon Espena

NAME		

No

Kms

Timing Chain

Yes

IGNATURE		