

•	Report ID:	27,804,823	Version:	1
	Created:	04 Dec 2025		

U	nuer	S Basi	C Condition Guide	Created: 04 Dec 2025	
Make:	Nissan	Model:	Latio	-	
Body Style:	Sedan	Year:	2014	Francisco	
Rego No.:	MYR517	Rego Expiry:	09 Dec 2025	Engine	
WoF Expiry:	16 Dec 2026	Odometer:	70,064 Kms	Oil level	
Good No.:	27804823	VIN:	7AT0DH90X20701883	Smoke & fumes	
Next Service:	76000	Service History:	No	Engine performance	
Note: This report is		,	<u> </u>	Noise	
This report is a guide	only. Consideration is made	e for age and mileage. Pa	arts have not been dismantled or n from cold. The Vendor recommends a	Coolant condition	
	ection prior to purchase an			Cooling performance	
Key				Radiator / Hoses (visual)	
S = Scratch R =	= Rust $C = C$	rack * = Deca	ls W = Significant scuffs	Transmission	
D = Dent PT	= Paint defect $P = P$	in dent SC = Stor	ne Chips	Operation	
		S	WSSC	Noise	
	$\overline{}$			Clutch	
	<u></u>		SW	CV joints	
CCW 1				Wheel bearings	
SC W				Brakes	
	MC 11.			Performance	
				Hand brake	
D SC	8			Tyres (lowest observed trea	
				Left front	
			(Q)	Right front	
				Left rear	
	W	osc ssc	W SDSC	Right rear	
Note: some defects a	and blemishes may not be	displayed in the diagra	m	Spare	
Body Inspection		. , , , , ,		Suspension	
				Suspension performance	
				Steering performance	
				Shock absorbers	
Conditions Duri	ing Body Inspection		Dry	Air Conditioning / Heater	
Under Carriage	e and Under Bonnet	Inspection Comm	ents	Operation	
				Electrical / Accessories	
				Head lights	
				Tail lights	
Interior Comm	ents			Indicators	

		Requires	
	OK	Attention	N/A
Engine			
Oil level	~		
Smoke & fumes	•		
Engine performance	~		
Noise	•		
Coolant condition	•		
Cooling performance	•		
Radiator / Hoses (visual)	<b>'</b>		
Transmission			
Operation	~		
Noise	<b>/</b>		
Clutch			<b>'</b>
CV joints	<b>/</b>		
Wheel bearings	<b>/</b>		
Brakes			
Performance	<b>/</b>		
Hand brake	<b>/</b>		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			6 mm
Right front		3	3.5 mm
Left rear			6 mm
Right rear			6 mm
Spare	Yes		
Suspension			
Suspension performance	<b>/</b>		
Steering performance	<b>/</b>		
Shock absorbers	<b>/</b>		
Air Conditioning / Heater			
Operation	<b>/</b>		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	1		
Wipers (front & rear)	~		
Window winder FL	/		
Window winder FR	<b>V</b>		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	/		
CD (basic test only)	1		
Number of keys	1		•
Central locking	1		
Remote locking	1		
Sat. nav. (basic test only)			1
D		l	$\vdash$

Road Conditions During Test Drive		Dry		
Engine Timing N	Mechanism	Timing Chain		
Evidence of Can	n Belt Replacement	Yes	No	Kms
Inspected by:	Melissa Wilson			
Published by:	Melissa Wilson			

have read and understood
this condition quide

Inspection Date: 04 Dec 2025

marks

Good

Good

Good

Seats:

Carpets:

Panels: Dashboard:

**General Comments** 

NAME			

Reversing camera