

Report ID:	27,805,193	Version:	1
Created:	03 Dec 2025		

U	ntuet	S Basi	c Condition Guide	Created:	
Make:	Honda	Model:	CRV		
Body Style:	SUV	Year:	2012	Engine	
Rego No.:	GNR280	Rego Expiry:	27 Mar 2026	<b>Engine</b> Oil level	
WoF Expiry:	17 Dec 2026	Odometer:	298,754 Kms	Smoke & 1	
Good No.:	27805193	VIN:	JHLRM4890CC203305		
Next Service:	308700	Service History:	No	Engine pe	
Note: This report is	not a warranty			Noise	
diagnostic testing un	dertaken. The vehicle has b	een driven up to 50km/	arts have not been dismantled or h from cold. The Vendor recommends a	Cooling p	
<u></u>	ection prior to purchase an	d this can be arranged i	or an additional charge.	Radiator /	
<b>Key</b> S = Scratch R	= Rust	rack *= Deca	ls W = Significant scuffs	Transmis	
	$\Gamma = \text{Paint defect}  \Gamma = \text{Pi}$		ne Chips	Operation	
				Noise	
SC	W	s sc s sc	W S SC	Clutch	
				CV joints	
			SSC	Wheel be	
S PT SC	S PT SC				
	19 11			Performa	
		-	S SC	Hand bral	
	R			Tyres (lov	
$\overline{}$				Left front	
			S PT SC	Right fron	
				Left rear	
S D SC	S	D SC S D SC	W S D SC	Right rear	
Note: some defects	and blemishes may not be	displayed in the diagra	am	Spare	
Body Inspecti				Suspensi	
Stone chips from	nt wind screenn			Suspensio	
				Steering p	
				Shock abs	
Conditions Dur	ing Body Inspection		Dry	Air Condi	
Under Carriage and Under Bonnet Inspection Comments					
				Electrical	
				Head ligh	
				Tail lights	
Interior Comm	nents			Indicators	
Seats:	wear			Dashboar	
Carpets:	Average			Wipers (fr	

	OK	Requires Attention	N/A
Engine	- OK	Accention	14// (
Oil level	<b>/</b>		
Smoke & fumes	1		
Engine performance	1		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	<b>/</b>		
Transmission		l	
Operation	·	l	
Noise	1		
Clutch			1
CV joints	1		
Wheel bearings	1		
Brakes		l	
Performance	V	I	
Hand brake	<b>/</b>		
Tyres (lowest observed tread	depth of	tvres)	
Left front		•	5.5 mn
Right front			5.5 mn
Left rear			3 mn
Right rear			3.5 mm
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater		1	
Operation	V		
Electrical / Accessories			
Head lights	<b>/</b>		
Tail lights	/		
Indicators	V		
Dashboard warning lights	V		
Wipers (front & rear)	/		
Window winder FL	1		
Window winder FR	V		
Window winder RL	/		
Window winder RR	V		
Rear view mirrors	1		
Radio (basic test only)	/		
CD (basic test only)		Ì	
Number of keys	2		
Central locking	/		
Remote locking	1		
Sat. nav. (basic test only)			1
Reversing camera	/	1	

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Melissa Wilson	
Published by:	Melissa Wilson	
Inspection Date:	03 Dec 2025	

I have read and understood	k
this condition quide	

Panels:

Dashboard:

**General Comments** 

Average

wear on steering wheel

NAME			