•	Report ID:	27,805,592	Version:	2
	Created:	10 Dec 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	V		
Engine performance	1		
Noise	/		
Coolant condition	V		
Cooling performance	V		
Radiator / Hoses (visual)	V		
Transmission			
Operation	V		
Noise	1		
Clutch			~
CV joints			1
Wheel bearings	1		
Brakes			
Performance	V		
Hand brake	1		
Tyres (lowest observed tread	depth of	tyres)	
Left front			3.0 m
Right front			3.0 m
Left rear		-	7.0 m
Right rear		-	7.0 m
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	<b>V</b>		Ι
Electrical / Accessories			
Head lights	V		Ι
Tail lights	1	1	
Indicators	1	1	
Dashboard warning lights	1		
Wipers (front & rear)	<b>V</b>		
Window winder FL	-		
Window winder FR	· ·	+	_
Window winder FK Window winder RL		1	<b>1</b>
Window winder RR		+	1
Rear view mirrors	J	-	_
	7		
Radio (basic test only)	1	1	
CD (basic test only)	2		
Number of keys	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	<u> </u>	1
Central locking	1		
Remote locking	-		
Sat. nav. (basic test only)		-	<b>,</b>
Reversing camera			

Make:	Hyundai	Model:	H1	
Body Style:	Van	Year:	2011	
Rego No.:	FTG402	Rego Expiry:	26 Jan 2026	
WoF Expiry:	16 Oct 2026	Odometer:	258,585 Kms	
Good No.:	27805592	VIN:	KMFWBX7JMBU326260	
Next Service:	267,000	Service History:	Yes	
ull mechanical insp ( <b>ey</b>	= Rust C = C	d this can be arranged fo		
D = Dent P	T = Paint defect P = Pi	in dent SC = Stor		
S SC W				
SDSC			SDSC	
SDSC	S	SC SD	SDSC	
s sc				
S SC	and blemishes may not be			
S SC lote: some defects  Body Inspecti	and blemishes may not be			
S SC	and blemishes may not be			

Interior Comments			
Seats:	hole in bolster and foam coming apart		
Carpets:	Carpets: Average		
Panels: scratches scuffs marks			
Dashboard: Average			
General Comments			

Road Condition	s During Test Drive	Wet
Engine Timing I	Mechanism	Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Gary Adams	
Published by:	Anna Zandstra	
Inspection Date:	25 Nov 2025	

I have read and understood	
this condition guide:	

NAME			

3	IG	N	Δ٦	ΓIJ	R	F	