

## **Basic Condition Guide**


•	Report ID:	27,805,908	Version:	1
	Created:	25 Nov 2025		

Make:	BMW	Model:	1161	
Body Style:	Hatchback	Year:	2012	
Rego No.:	PCN909	Rego Expiry:	07 Dec 2025	
WoF Expiry:	21 Feb 2026	Odometer:	120,329 Kms	
Good No.:	Good No.: 27805908 VIN:		WBA1A12050J205440	
Next Service: 126,000 Kms Service History			No	
Note: This report is not a warranty  This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.				

Note: This	report is not a	warranty
------------	-----------------	----------

## Kev

Rey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Headlights have moisture inside

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Oil leak (belly pan is covered in oil)

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	

## **General Comments**

Smoke coming from turbo/exhaust manifold when warm (could be oil residue burning

Passenger door central locking doesn't work (has to be manually locked and unlocked)

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Logan Lane	
Published by:	Janine Bell	
Inspection Date:	22 Nov 2025	

I have read and understood		
this condition guide:	NAME	

	ОК	Requires Attention	N/A
Engine		7.000.00.0	
Oil level	V		
Smoke & fumes		<b>V</b>	
Engine performance	1		
Noise	1		
Coolant condition	\( \tau \)		
Cooling performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	<b>/</b>		
Noise	<b>/</b>		
Clutch			~
CV joints	<b>/</b>		
Wheel bearings	<b>/</b>		
Brakes			
Performance	•		
Hand brake	<b>/</b>		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		(	6.1 mm
Right front		(	6.1 mm
Left rear			1.0 mm
Right rear			1.5 mm
Spare	N/A		
Suspension	1		
Suspension performance	~		
Steering performance	~		
Shock absorbers	<b>/</b>		
Air Conditioning / Heater			
Operation	<b>'</b>		
Electrical / Accessories	1		
Head lights	~		
Tail lights	1		
Indicators	<b>V</b>		
Dashboard warning lights			
Wipers (front & rear)	\( \tau \)		
Window winder FL	<b>/</b>		
Window winder FR	<b>/</b>		
Window winder RL			
Window winder RR	•		
Rear view mirrors	•		
Radio (basic test only)	•		
CD (basic test only)	/		
Number of keys	1	Γ.	
Central locking		•	
Remote locking	•		
Sat. nav. (basic test only)			
Reversing camera	<b>'</b>		