

Basic Condition Guide

Report ID:	27,806,625	Version:	1
Created:	24 Nov 2025		

N/A

7.0 mm 8.0 mm 6.0 mm

	Jillei	<u> </u>		Created:	24 Nov 2025		
Make:	Mitsubishi	Model:	Triton			1	Requires
Body Style:	Utility	Year:	2014	Function		OK	Attention
Rego No.:	HLZ540	Rego Expiry:	22 Sep 2026	Engine Oil level			
WoF Expiry:	26 Aug 2026	Odometer:	279,644 Kms			/	
Good No.:	27806625	VIN:	MMAJRKA40FD006332	Smoke & fumes Engine performance		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
Next Service:	289600	Service History:	Yes		g p		
Note: This report is r	not a warranty	,		Noise	1	/	
his report is a guide o	only. Consideration is made	e for age and mileage. Pa	arts have not been dismantled or n from cold. The Vendor recommends a	Coolant co		/	
	ction prior to purchase and				erformance	/	
Кеу					Hoses (visual)	/	
	Rust $C = C$			Transmission			
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips			Operation		/		
		S P SC		Noise		V	
$\overline{}$	$\overline{}$	T		Clutch			
	(M)-		D	CV joints		/	
—— 1				Wheel bea	rings	/	
$-\!\!\!-\!\!\!\!-\!$				Brakes			
111	Mr II I			Performan	ce	/	
1 1				Hand brak	e	/	
SC	R			Tyres (lowest observed tread depth of tyres)			
J				Left front			7
				Right front		8	
	\angle $\overline{}$			Left rear		6	
][D SC		Right rear		6	
Note: some defects a	nd blemishes may not be	displayed in the diagra	ım	Spare		Yes	
Body Inspection	on Comments			Suspensio	n		
				Suspensio	n performance	V	
				Steering p	erformance	~	
				Shock abso	orbers	1	
Conditions Duri	ng Body Inspection		Dry	Air Condit	tioning / Heater	,	
Under Carriage	e and Under Bonnet	Inspection Comm	ents	Operation		/	
Surface rust on u	under body of Vehicle).		Electrical	/ Accessories		
				Head light	S	V	
				Tail lights		~	
Interior Comm	ents			Indicators		1	
Seats:	Average			Dashboard	d warning lights	1	
Carpets:	Average			Wipers (fro	ont & rear)	1	
Panels:	Average			Window w	inder FL	1	
Dashboard: Good					rinder FR	1	
General Comm	nents		Window w	inder RL	1		
				Window w	inder RR	1	
				Rear view i		1	
					ic test only)	1	
Road Condition	s During Test Drive	Dry		CD (basic t		1	

	Road Condition	s During Test Drive	Dry		
ĺ	Engine Timing N	Mechanism	Cambelt		
	Evidence of Cam Belt Replacement		Yes	✓ No	Kms
	Inspected by:	Chris Buckley			
	Published by:	Josh Dempster			
	Inspection Date:	24 Nov 2025			
•				-	

I have read and understood this condition guide:

NAME

SIGNATURE

Number of keys Central locking

Remote locking

Sat. nav. (basic test only)
Reversing camera

2

<u>ノ</u>