

## **Basic Condition Guide**

•	Report ID:	27,807,263	Version:	1
	Created:	16 Dec 2025		


			Requires	
		OK	Attention	N/A
	Engine			
	Oil level	/		
B054154	Smoke & fumes	/		
	Engine performance	/		N/A  7.0 mm  1.0 mm  1.0 mm
	Noise	/		
antled or	Coolant condition	/		
recommends a	Cooling performance	/		
	Radiator / Hoses (visual)	<b>/</b>		
nificant scuffs	Transmission			
	Operation	<b>/</b>		
	Noise	/		
SC	Clutch			/
sc	CV joints	/		
SC	Wheel bearings	/		
	Brakes			
	Performance	·		
	Hand brake	1		
	Tyres (lowest observed tread	denth of	tvres)	
8	Left front	deptiroi	•	7 0 mi
	Right front			
	Left rear		-	
	Right rear	\/		i.U mi
	Spare	Yes		
	Suspension			
	Suspension performance	/		
	Steering performance	/		
	Shock absorbers	/		
	Air Conditioning / Heater		1	
	Operation	<b>/</b>		
	Electrical / Accessories			
	Head lights	<b>/</b>		
	Tail lights	<b>/</b>		
	Indicators	<b>/</b>		
	Dashboard warning lights	<b>/</b>		
	Wipers (front & rear)	/		
	Window winder FL	V		
	Window winder FR	1		
	Window winder RL	·		
	Window winder RR	1		
	Rear view mirrors	1		
		V		
	Radio (basic test only)	1		
	CD (basic test only)	•		
	Number of keys	2		
Kms	Central locking	/	-	
	Remote locking	-		
	Sat. nav. (basic test only)			~
	Reversing camera		1	

	A   P				
Make:	Audi	Model:	A1		
Body Style:	Hatchback	Year:	2016		
Rego No.:	JQA590	Rego Expiry:	10 Feb 2026		
WoF Expiry:	05 Dec 2026	Odometer:	37,255 Kms		
Good No.:	27807263	VIN:	WAUZZZ8X0GB054154		
Next Service:	47,000 km	Service History:	No		
Note: This report is not a warranty					

This report is a guide only. Consideration is made for age and mileage. Parts have not been di diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendon and Cold. The Vendon are the vehicle has been driven up to 50km/h from cold. full mechanical inspection prior to purchase and this can be arranged for an additional char

## Key

\* = DecalsS = ScratchR = RustC = CrackW =D = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram  $\,$ 

## **Body Inspection Comments**

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		

Freshly serviced.

2 new tyres.

Front wheel drive.

Interior Comments	
Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good
General Comments	

		_		
Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	<b>V</b> No	Kms
Inspected by:	Imraan Bryant			
Published by:	Erin White			
Inspection Date:	28 Nov 2025			

I have read and understood this condition guide:

NAME			

S	IG	N	ΔT	ΓIJ	R	F