

•	Report ID:	27,808,018	Version:	1
	Created:	25 Nov 2025		


	OK	Requires Attention	
Engine	OK .	Attention	IV/A
Oil level	1		
Smoke & fumes	1		
Engine performance	~		
Noise	V		
Coolant condition	/		
Cooling performance	V		
Radiator / Hoses (visual)	~		
Transmission			
Operation	/		
Noise	/		
Clutch	V V		
CV joints	~		
Wheel bearings	/		
Brakes			_
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			3 mm
Right front			3 mm
Left rear			2 mm
Right rear			3 mm
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	V		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	1		
Radio (basic test only)			
CD (basic test only)	V		
Number of keys	1		
Central locking	1		
Remote locking	/		
Sat. nav. (basic test only)			~
Reversing camera			~

Hyundai	Model:	Getz
Hatchback	Year:	2004
CFJ947	Rego Expiry:	30 Nov 2025
24 Jun 2026	Odometer:	173,649 Kms
27808018	VIN:	KMHBT51HR4U241449
177,340kms	Service History:	Yes
	Hatchback CFJ947 24 Jun 2026 27808018	Hatchback Year: CFJ947 Rego Expiry: 24 Jun 2026 Odometer: 27808018 VIN:

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Chipped windscreen.

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Engine oil leaks.

Interior Comments

Seats:	Average				
Carpets:	Average				
Panels:	Gear stick boot we	Gear stick boot worn.			
Dashboard:	Average				
General Comn	General Comments				
Service history to 2011 only. Radio not tuning into FM stations. Noisy A/C pump. 5 speed manual Getz hatch.					
Road Condition	Road Conditions During Test Drive Dry				
Engine Timing Mechanism		Cambelt			
Evidence of Cam Belt Replacement		Yes	✓ No	Kms	
Inspected by:	Daryll Timms				
Published by:	Daryll Timms				
Inspection Date:	: 25 Nov 2025				

I have read and understood
this condition quide

NAME			

SIGNATURE		