

Report ID:	27,809,080	Version:	2
Created:	03 Dec 2025		

		Dooi	Basic Condition Guide		27,809,080	Ve	rsion: 2	
	urner	S Basi	C Condition Guide	Created:	03 Dec 2025			
Make:	Suzuki	Model:	Swift				Requires	
Body Style:	Hatchback	Year:	2011			OK	Attention	N/A
	FTS276		15 Feb 2026	Engine				
Rego No.:	17 Dec 2026	Rego Expiry:	122,535 Kms	Oil level		~		
WoF Expiry:		Odometer:	JSAFZC82S00100260	Smoke & fu	mes	~		
Good No.:	27809080	VIN:		Engine per	formance	~		
	Next Service: 135,000 Service History: No					~		
Note: This report is This report is a guide	only. Consideration is made	e for age and mileage. Pa	arts have not been dismantled or	Coolant co	ndition	~		
diagnostic testing un	idertaken. The vehicle has b ection prior to purchase an	een driven up to 50km/h	from cold. The Vendor recommends a	Cooling pe	rformance	~		
Key				Radiator / F	loses (visual)	/		
	= Rust C = C	rack *= Deca	ls W = Significant scuffs	Transmissi	on			
D = Dent P1	$\Gamma = Paint defect P = Paint defect$	in dent SC = Stor	ne Chips	Operation		/		
SSC		s s		Noise		~		
330		3 3		Clutch				/
	(A)		S	CV joints		1		
	MA UT			Wheel bearings 🗸				
SW				Brakes				
				Performand	ce	1		
			S	Hand brake	1	1		
S PT SC	18			Tyres (lowest observed tread depth of tyres)				
				Left front	Left front 1.5 mm			1.5 mm
						2.0 mr		2.0 mm
						5.5 mn		
S PT SC S P S						5.5 mm		
Note: some defects and blemishes may not be displayed in the diagram				Spare Yes				
Body Inspection		. , , , , ,		Suspensio	n			
Dent in left sill				Suspension	performance	1		
Moisture in left taillight Rear bumper right corner popped out				Steering pe		1		
				Shock abso	rbers	1		
Conditions During Body Inspection Dry			Air Conditi	ioning / Heater				
Under Carriage and Under Bonnet Inspection Comments						V		
Oil seepage from	m A/C compressor	. ·		Electrical /	Accessories	-		
				Head lights	;	1		
				Tail lights		1		
Interior Comments				Indicators		~		
Seats: Average			Dashboard	warning lights	1			
Carpets:			Wipers (fro		1			
Panels: Average			Window wi		1			
Dashboard: Average			Window wi	nder FR	1			
General Comp	General Comments			Window wi	nder RL	1		

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Timing Chai	n	
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Samuel Weir			
Published by:	Desian Robb			

I have read and understood this condition guide:

Inspection Date: 27 Nov 2025

Jack, no tools

NAME			

SIGNATURE			

1

• 1

1

•

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)