

Basic Condition Guide


•	Report ID: 27,809,411		Version:	1
	Created:	27 Nov 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	V		
Noise	/		
Coolant condition	V		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	/		
Clutch			~
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		· ·	10 mm
Right front			10 mm
Left rear			10 mm
Right rear			9.5 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater		,	
Operation	/		
Electrical / Accessories		•	
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	1		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			~
Number of keys	2		
Central locking	1		
Remote locking	/		
Sat. nav. (basic test only)	/		
Reversing camera	/		
-			

Make:	Toyota	Model:	Fortuner
Body Style:	SUV	Year:	2022
Rego No.:	PAK146	Rego Expiry:	07 Feb 2026
WoF Expiry:	30 Jan 2026	Odometer:	187,646 Kms
Good No.:	27809411	VIN:	MR0BA3FS501125328
Next Service:	187000	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

ney				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Conditions During Body Inspection

Under Carriage and Under Bonnet Inspection Comments

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Good	
General Comments		

Road Conditions During Test Drive Dry Timing Chain

Engine Timing Mechanism Evidence of Cam Belt Replacement No Yes Kms Kris Milne Inspected by: Published by: Kris Milne Inspection Date: 27 Nov 2025

I have read and	understood
this condition of	uuide.

NAME			

ς	10	٩N	JA	١Т	U	RI	F