

## **Basic Condition Guide**

Report ID:	27,811,220	Version:	3	
Created:	04 Dec 2025			

	Dillei	<u> </u>		Created:	04 Dec 2025					
Make:	Ford	Model:	Ranger				Requires			
Body Style:	Utility	Year:	2023			OK	Attention	N/A		
Rego No.:	QAN944	Rego Expiry:	22 Jun 2026	Engine						
WoF Expiry:	31 May 2026	Odometer:	61,282 Kms	Oil level		<b>✓</b>				
Good No.: 27811220		VIN:	MPBCMFF60PX478558	Smoke & f	umes	<b>✓</b>				
Next Service:	75000	Service History:	Yes	Engine performance		<u> </u>				
		Service mistory.	Noise	Noise						
Note: This report is This report is a guide	only. Consideration is mac	de for age and mileage.	Coolant co	ondition	<u> </u>					
diagnostic testing ur full mechanical insp	ndertaken. The vehicle has l ection prior to purchase ar	been driven up to 50km nd this can be arranged	Cooling p	erformance	<u> </u>					
Key				Radiator /	Hoses (visual)	<u> </u>				
S = Scratch R	= Rust $C=0$	Crack *= Dec	als W = Significant scuffs	Transmis	sion					
D = Dent $P$	T = Paint defect P = F	Pin dent $SC = Storage$	one Chips	Operation	1	<b>/</b>				
S		S SD		Noise		<b>/</b>				
	$\overline{}$			Clutch				~		
	(M)-			CV joints		<b>/</b>				
SC (		+		Wheel bea	arings	<b>/</b>				
SC A				Brakes						
				Performa	nce	<b>/</b>				
				Hand brak	ce	/				
SC				Tyres (low	Tyres (lowest observed tread depth of tyres)					
				Left front			7	7.0 mn		
			(Q)	Right fron	t		8	3.0 mn		
	$\angle$			Left rear		2.0 mm				
		<u>s</u> <u>s</u>		Right rear		3.0 mm				
Note: some defects	and blemishes may not be	e displayed in the diag	ram	Spare		Yes				
Body Inspecti	on Comments			Suspensi	on					
Windscreen sto	one chips.			Suspensio	n performance	<b>/</b>				
				Steering p	erformance	<b>/</b>				
				Shock abs	orbers	<b>/</b>				
Conditions Du	ring Body Inspection		Dry	Air Condi	Air Conditioning / Heater					
Under Carriag	je and Under Bonne	t Inspection Com	ments	Operation	Operation 🗸					
4Wheel drive.				Electrical	/ Accessories					
				Head ligh	ts	<b>/</b>				
				Tail lights		<b>/</b>				
Interior Comn	nents			Indicators		<b>'</b>				
Seats:	Good			Dashboar	d warning lights	<b>/</b>				
Carpets:	Good			Wipers (fr	ont & rear)	~				
Panels:	Good			Window v	Window winder FL					
Dashboard: Good					vinder FR	~				
General Comr	ments		Window v	vinder RL	<b>/</b>					
				Window v	vinder RR	<b>/</b>				
				Rear view	mirrors	<b>/</b>				
				Radio (bas	sic test only)	<u> </u>				
Road Condition	ns During Test Drive	Dry	CD (basic	-			1			
Engine Timing		Timing Chain		Number	-	2	1			
	m Belt Replacement	Yes	No Kms	Central lo		<b>/</b>				
Inspected by:	Rajesh Mayan			Remote lo	9	<u> </u>				
Published by:	Ben Nicholson				pasic test only)	-		1		
Instantian Data 20 Nov 2025				54	and test only)			Ť		

I have read and understood this condition guide:

Inspection Date: 28 Nov 2025

NAME \_\_\_\_\_

SIGNATURE

Reversing camera