

## Basic Condition Guide

-	Report ID: 27,811,573		Version:	1
	Created:	05 Dec 2025		

ca II	ntuet	C Basi	c Condition Guide	neporeib.	27,011,070	1	1510111	
		<b>J</b>		Created:	05 Dec 2025			
Make:	Honda	Model:	Airwave			01/	Requires	
Body Style:	dy Style: Wagon Year: 2007		2007	Engine		OK	Attention	N/A
Rego No.:	LKR860	Rego Expiry:	30 Nov 2026	Oil level		<b>/</b>		
WoF Expiry:	17 Oct 2026	Odometer:	192,184 Kms	Smoke & fu	ımos	1		
Good No.:	27811573	VIN:	7AT08GBNX18120732	Engine per		1		
Next Service:	198,000kms	Service History:	No	Noise	Torriance	V		
Note: This report is	not a warranty			Coolant co	ndition	V		
This report is a guide diagnostic testing un	only. Consideration is made dertaken. The vehicle has b	e for age and mileage. Pa een driven up to 50km/l	arts have not been dismantled or n from cold. The Vendor recommends a		erformance	V		
full mechanical inspe	ection prior to purchase an	d this can be arranged f	or an additional charge.		Hoses (visual)	1		
Key				Transmiss				
	= Rust $C = C$ $\Gamma$ = Paint defect $P = P$		3	Operation	1011	<b>/</b>	1	
D=Defit Fi	= Paint delect P = P	111 dent 3C = 310	nie Chips	Noise		V		
<u>s</u>	S S	SP SD	SP	Clutch				
				CV joints		·		
	$\sim$		$(\bigcirc)$	-	rings	1		
S SC				Wheel bearings  Brakes				
MID					CO.	<b>/</b>	<u> </u>	
		1	P SC	Performan Hand brak		~		
P SC	lo II			Tyres (lowest observed tread depth of tyres)				
1 30 6				Left front	est observed tread o			3.5 mm
			DPT	Right front				1.5 mm
				Left rear	•			5.0 mm
S	W	DP SD	SS	Right rear		5.0 mm		
Notas como defecto	and blomishes may not be	displayed in the diagra		Spare		N/A		
Body Inspection	and blemishes may not be	displayed in the diagra	im	Suspension	nn	14//		
Paint is flaking of	_			-	n performance	V		
ŭ	J			-	erformance	1		
				Shock abso		1		
Conditions Dur	ing Body Inspection		Dry		ioning / Heater			
Under Carriage and Under Bonnet Inspection Comments  Leaking from transmission.					g, rreater	V		
					Operation   Electrical / Accessories			
· ·				Head light		·		
				Tail lights		1		
Interior Comm	nents			Indicators		1		
Seats:	Good				l warning lights	1		
Carpets:	Good			Wipers (fro		1		
30. p = 131				, 2013 (110		Ļ,		<b>—</b>

	Interior Comments				
	Seats:	od			
	Carpets:	Good			
	Panels:	Left rear door trim is scuffed.			
Dashboard: Good		Good			
	General Comments				

Rear seat centre belt buckle case is cracked. Rear window washer is not operating.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Yuki Itohara	
Published by:	Glen Charlton	
Inspection Date:	01 Dec 2025	

I have read and understood
this condition guide:

NAME			

SIGNATURE			

1

V

1

1 1

1

1

Window winder FL Window winder FR Window winder RL

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera