

•	Report ID:	27,812,147	Version:	1	
	Created:	03 Dec 2025			

ea Ti	urner	Rasi	c Condition Guide	Report ID:	27,812,147	Ve	rsion:	1	
	Ulliel	<u> </u>		Created:	03 Dec 2025				
Make:	Mazda	Model:	Mazda2				Requi		
Body Style:	Hatchback	Year:	2015	OK		OK	Attent	ion	N/A
Rego No.:	JEJ24	Rego Expiry:	15 Jun 2026	Engine					
WoF Expiry:	05 Feb 2026	Odometer:	123,670 Kms	Oil level				$\dashv$	
Good No.:	27812147	VIN:	MM0DJ2HAA0W136226	Smoke & fumes				$\dashv$	
Next Service:	133541	Service History:	Yes	Engine performance		<u> </u>		$\dashv$	
Note: This report is not a warranty					Noise Coolant condition			$\dashv$	
This report is a guide	e only. Consideration is mac ndertaken. The vehicle has l					$\dashv$			
	pection prior to purchase ar				erformance	<i>\</i>		$\dashv$	
Key					Hoses (visual)	<b>✓</b>	<u> </u>		
		Crack * = Deca		Transmiss	ion		<u> </u>		
D = Dent P	T = Paint defect P = F	Pin dent SC = Sto	ne Chips	Operation				$\dashv$	
		SC		Noise		<b>✓</b>		$\dashv$	
$\overline{}$				Clutch			-		
			S	CV joints		<i>\</i>	-		
S SC				Wheel bearings					
$\sim$ $\rho$	18			Brakes					
				Performan		/	-	_	
				Hand brak		<b>✓</b>			
SC				Tyres (lowest observed tread depth of tyres)					
								.7 mm	
					Right front 6.4 m			.4 mm	
				Left rear	ft rear 6.4 m			.4 mm	
		SC (		Right rear				6	.4 mm
Note: some defects	and blemishes may not b	e displayed in the diagra	am	Spare		Yes			
Body Inspecti	ion Comments			Suspensio	n				
Minor stonechip	ps on windscreen			Suspension	n performance	<b>/</b>			
				Steering p	erformance	<b>/</b>			
				Shock abso	orbers	<b>/</b>			
Conditions Du	ring Body Inspection		Dry	Air Condit	ioning / Heater				
Under Carriag	ge and Under Bonne	t Inspection Comm	nents	Operation		<b>/</b>		$\underline{\hspace{1cm}}$	
Front wheel driv	ve			Electrical / Accessories					
				Head light	S		<b>/</b>		
				Tail lights		•		J	
Interior Comm	nents			Indicators		/			
Seats:	Good			Dashboard warning lights 🗸		/			
Carpets:	Good		Wipers (fro	nt & rear)	/				
Panels: Good			Window w	inder FL	/		T		
Dashboard: Good			Window w	inder FR	<b>✓</b>				
General Comments					inder RL	<b>✓</b>		$\Box$	
Drives well					inder RR	<b>/</b>		$\neg$	
				Rear view ı	mirrors	<b>✓</b>		$\dashv$	
							-	$\rightarrow$	

I have read and understood this condition guide:

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Inspection Date: 03 Dec 2025

Engine Timing Mechanism

Inspected by:

Published by:

NAME			

No

Dry

Cameron Senior-Arnold

Holden Milne-Smith

Timing Chain

Yes

SIGNATURE		

1

2

1

1

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Kms