•	Report ID:	27,812,841	Version:	2
	Created:	12 Dec 2025		

OK

1

1

1

1

Requires Attention

N/A

OT.			a Canditian Cuida	Report ID:	27,812,8
	nuer	S Basi	c Condition Guide	Created:	12 Dec 2
Make:	Lexus	Model:	GS300		
Body Style:	Sedan	Year:	2007	Engine	
Rego No.:	DZE769	Rego Expiry:	13 Jul 2026	Oil level	
WoF Expiry:	25 Dec 2026	Odometer:	171,337 Kms	Smoke & fu	ımes
Good No.:	27812841	VIN:	JTHBH96S205045618	Engine per	formance
Next Service:	181000	Service History:	No	Noise	
Note: This report is	•			Coolant co	ndition
diagnostic testing un	only. Consideration is made dertaken. The vehicle has b ection prior to purchase an	een driven up to 50km/ł	arts have not been dismantled or n from cold. The Vendor recommends a	Cooling performance	
	ection prior to purchase an	u triis can be arranged i	or an additional charge.	Radiator / H	loses (visua
<b>Key</b> S = Scratch R :	= Rust	rack *=Deca	ls W = Significant scuffs	Transmissi	ion
	= Paint defect $P = P$	in dent SC = Stor	•	Operation	
SC	10/	SSC	WS	Noise	
50	W	3 30	W S	Clutch	
	(A)		SD	CV joints	
				Wheel bear	rings
S SC				Brakes	
	Mr II			Performan	ce
1 []				Hand brake	<u> </u>
PT SC	8			Tyres (lowe	est observe
				Left front	
			(Q)	Right front	
	$\angle$			Left rear	
	PT	<u>s</u>		Right rear	

## **Body Inspection Comments**

Bonnet stays need Regas, R/H B pillar inner  $\operatorname{Trim}\nolimits$  Torn .

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Interior Comments			
Seats:	Good		
Carpets:	Good		
Panels:	Average		
Dashboard:	Good		
General Comments			

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Chris Buckley	
Published by:	Liam Walls	
Inspection Date:	03 Dec 2025	

I have read and understood		
this condition guide:	NAME	

Radiator / Hoses (visual)	<b>/</b>				
Transmission					
Operation	<b>'</b>				
Noise	<b>/</b>				
Clutch			V		
CV joints	/				
Wheel bearings	<b>/</b>				
Brakes					
Performance	/				
Hand brake	<b>/</b>				
Tyres (lowest observed tread d	epth of	tyres)			
Left front		6	6.0 mm		
Right front		5	5.0 mm		
Left rear		6	3.0 mm		
Right rear		6	3.0 mm		
Spare	Yes				
Suspension					
Suspension performance	•				
Steering performance	•				
Shock absorbers	•				
Air Conditioning / Heater					
Operation	<b>'</b>				
Electrical / Accessories					
Head lights	•				
Tail lights	1				
Indicators	V				
Dashboard warning lights					
Wipers (front & rear)	•				
Window winder FL	•				
Window winder FR	1				
Window winder RL	/				
Window winder RR	/				
Rear view mirrors	•				
Radio (basic test only)	/				
CD (basic test only)	•				
Number of keys	3				
Central locking	•				
Remote locking	•				
Sat. nav. (basic test only)			~		
Reversing camera	•				

SIGNATURE			