


Make:	Mazda	Model:	Axela
Body Style:	Sedan	Year:	2013
Rego No.:	NPL500	Rego Expiry:	21 Jan 2026
WoF Expiry:	31 Oct 2026	Odometer:	193,700 Kms
Good No.:	27813570	VIN:	7AT0C13JX21599323
Next Service:	Unknown	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Dent in left sill
Glue residue on bumper and left guard
Large stone chips in windscreen
B pillar trims flaking off

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Coolant low
Rear tyres wearing on inside edge
Lowering springs fitted

Interior Comments

Seats: Covers on seats, drivers cover torn
Carpets: Average
Panels: Average
Dashboard: Average

General Comments

Rear view mirror delaminating. Centre console lid catch broken. Key blade broken.
Humming noise at speed

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms
Inspected by:	Samuel Weir
Published by:	James Scott
Inspection Date:	28 Nov 2025

Report ID:	27,813,570	Version:	1
Created:	28 Nov 2025		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			5.0 mm
Right front			5.0 mm
Left rear			3.0 mm
Right rear			3.0 mm
Spare		N/A	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood
this condition guide:

NAME _____

SIGNATURE _____