

Basic Condition Guide

Report ID:	27,813,673	Version:	1
Created:	02 Dec 2025		

				Created	
Make:	Haval	Model:	H6		
Body Style:	SUV	Year:	2021	Engine	
Rego No.:	NPG377	Rego Expiry:	29 Dec 2025	Oil leve	
WoF Expiry: 12 Nov 2026		Odometer:	73,594 Kms	Smoke	
Good No.:	27813673	VIN:	LGWEF6A57MH955166	Engine	
Next Service:	87,000	Service History:	No	Noise	
ote: This report is	not a warranty			Coolan	
iagnostic testing un		een driven up to 50km/l	arts have not been dismantled or h from cold. The Vendor recommends a or an additional charge	Cooling	
(ey				Radiato	
•	= Rust	Crack *= Deca	ls W = Significant scuffs	Transn	
= Dent P1	Γ = Paint defect $P = P$	in dent SC = Stor	3	Operat	
s		SP SP	SDR	Noise	
		3F 3F	J J J K	Clutch	
	<u></u>		SW	CV join	
0.00.14				Wheel	
s sc w				Brakes	
			ssc	Perforr	
			330	Hand b	
S P SC				Tyres (
				Left fro	
			S	Right fr	
	\leq			Left rea	
		SP SP	S	Right re	
ote: some defects	and blemishes may not be	displayed in the diagra	ım	Spare	
Body Inspecti	on Comments			Suspei	
				Suspen	
				Steerin	
				Shock a	
Conditions Dur	ing Body Inspection		Dry	Air Cor	
Under Carriag	e and Under Bonnet	Inspection Comm	ients	Operat	
				Electri	
				Head li	
				Tail ligh	
Interior Comm	nents			Indicat	
Seats:	Good			Dashbo	
Carpets:	Good				
Panels:	Good				
Dashboard: Good					
General Comn	nents			Windo	
				Windo	
				Rear vie	
				Radio (
Road Conditions During Test Drive Dry					
Engine Timing	Mechanism	Timing Chain		Numbe	

	OK	Requires Attention	
Engine	<u> </u>	Attention	IN/A
Oil level	1		
Smoke & fumes	V		
Engine performance			
Noise	V		
Coolant condition	V		
Cooling performance	\(\tau \)		
Radiator / Hoses (visual)	/		
Transmission			
Operation	V		
Noise	/		
Clutch			~
CV joints	V		
Wheel bearings	1		
Brakes			
Performance	✓		
Hand brake	V		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		7	7.5 mm
Right front		7	7.5 mm
Left rear		3	3.5 mm
Right rear		3	3.5 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	/		L
Electrical / Accessories		,	
Head lights	/		
Tail lights	/		
Indicators	V		
Dashboard warning lights			
Wipers (front & rear)	/		
Window winder FL	•		
Window winder FR	/		
Window winder RL	•		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			
Number of keys	2	ı	
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			
Reversing camera	•		

I have read and understood this condition guide:

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 02 Dec 2025

Samuel Weir

James Scott

NAME

Yes

No

SIGNATURE

Kms