

•	Report ID: 27,813,878		Version:	3
	Created:	27 Nov 2025		

		Doo!	a Canaditian Cuida	ricport ib.	27,013,070	l vci	131011.	
	nuel	S Basi	c Condition Guide	Created:	27 Nov 2025			
Make:	LDV	Model:	V80				Requires	NI/A
Body Style:	Van	Year:	2020	Engine		OK	Attention	N/A
Rego No.:	NEK727	Rego Expiry:	29 Nov 2025	Oil level		<b>V</b>		
WoF Expiry:	22 Nov 2026	Odometer:	92,258 Kms	Smoke & fu	mas	<i>'</i>		
Good No.:	27813878	VIN:	LSKG4GL15LA088830			<i>'</i>		
Next Service:	97767	Service History:	Yes	Engine perf	ormance	<i>'</i>		
Note: This report is r	not a warranty			Noise	altatia	<i>'</i>		
This report is a guide of	only. Consideration is made	e for age and mileage. Pa	rts have not been dismantled or I from cold. The Vendor recommends a	Coolant cor		<i>'</i>		
ull mechanical inspe	ection prior to purchase an	d this can be arranged fo	or an additional charge.	Cooling per		•		
Кеу					oses (visual)	/		
	= Rust C = C			Transmissio	on			
D = Dent PT	= Paint defect $P = P$	in dent SC = Stor	ne Chips	Operation		/		
S	W	W DW	DRW	Noise		/		
				Clutch				<b>✓</b>
			DW	CV joints		/		
PT SC W				Wheel bear	ngs	<b>/</b>		
HI HI	A TO		1	Brakes				
RP RP				Performanc	e	~		
						<b>/</b>		
S R SC	M - I			Tyres (lowest observed tread depth of tyres)				
DW				Left front			9	9.0 mm
				Right front				1.0 mm
				Left rear		4.0 n		1.0 mm
D W	W	S D		Right rear		5.0 r		5.0 mm
Note: some defects a	and blemishes may not be	displayed in the diagra	m	Spare		Yes		
Body Inspection	on Comments			Suspension	1			
	ne crack not in CVA			Suspension	performance	/		
Driver door ched	ck strap clicking nt wing mirror housing	a cracked / Pight In	dicator long cracked	Steering pe	rformance	/		
•	ted and scuffed	g cracked / Right in	dicator lens cracked	Shock abso	bers	/		
Conditions Duri	ing Body Inspection		Dry	Air Conditi	oning / Heater			
Under Carriage and Under Bonnet Inspection Comments			Operation		/			
Underbody oxidation				Electrical / Accessories				
				Head lights		<b>/</b>		
				Tail lights		/		
Interior Comm	ents			Indicators		/		
Seats:	Average			Dashboard	warning lights	/		
Carpets:	Average			Wipers (fror		/		
Panels:	Average			Window wii		1		
Dashboard:	Average		·	Window wii	nder FR	<b>/</b>		

	/go	
Dashboard:	Average	
General Comm	ents	
Partial service his Stained seats	story	
Road Conditions	s During Test Drive	Dry
Engine Timing N	Леchanism	Timing Chain

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Timing Chain		
Evidence of Cam Belt Replacement		Yes	No Kms	
Inspected by: Sione Mae				
	Published by: Bruce Screaton			
	Inspection Date:	26 Nov 2025		

ıŀ	nave	read	and	unde	ersto	od
tŀ	nis co	nditi	on a	uide	:	

NAME			

SIGNATURE		

•

1 2

1

•

1

Window winder RL Window winder RR Rear view mirrors

Radio (basic test only) CD (basic test only)

Sat. nav. (basic test only)

Reversing camera

Number of keys

Central locking Remote locking