

Report ID: 27,814,343		Version:	2
Created:	02 Dec 2025		

U	ntuer	S Basi	C Condition Guide	Created: 02 Dec 2025	
Make:	BMW	Model:	Z4		
Body Style:	Convertible	Year:	2006	Engine	
Rego No.:	RKK638	Rego Expiry:	08 Oct 2026	Oil level	
WoF Expiry:	08 Oct 2026	Odometer:	187,361 Kms	Smoke & fumes	
Good No.:	27814343	VIN:	WBABU520X0LP17203		
Next Service:		Service History:	No	Engine performance Noise	
Note: This report is	not a warranty			Coolant condition	
diagnostic testing un	dertaken. The vehicle has b	een driven up to 50km/l	arts have not been dismantled or n from cold. The Vendor recommends a	Cooling performance	
· ·	ection prior to purchase and	d this can be arranged f	or an additional charge.	Radiator / Hoses (visual)	
Key	D		l- W C:: C:	Transmission	
	= Rust $C = C$ Γ = Paint defect $P = Pi$		3	Operation	
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	D	DT.	Noise	
PSC	W	P	PT	Clutch	
			SPT	CV joints	
()	MA OF			Wheel bearings	
D PT SC				Brakes	
				Performance	
	Hand brake				
SC OR				Tyres (lowest observed tre	
				Left front	
			PT	Right front	
	\angle			Left rear	
P	<u>S</u>		SPT	Right rear	
Note: some defects	and blemishes may not be	displayed in the diagra	m	Spare	
Body Inspection	on Comments			Suspension	
Roof can only b	e open/closed manua	Illy, Condensation i	n Both Front Fog Lights.	Suspension performance	
				Steering performance	
				Shock absorbers	
Conditions Dur	ing Body Inspection		Dry	Air Conditioning / Heater	
Under Carriag	e and Under Bonnet	Inspection Comm	ents	Operation	
Oil leak lower er	ngine Area.			Electrical / Accessories	
				Head lights	
				Tail lights	
Interior Comm	nents			Indicators	
Seats:	Average			Dashboard warning lights	
Carpets:	Average			Wipers (front & rear)	

		Requires	
	OK	Attention	N/A
Engine			
Oil level			'
Smoke & fumes	~		
Engine performance	~		
Noise	•		
Coolant condition	/		
Cooling performance	~		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	/		
Clutch			'
CV joints	1		
Wheel bearings	1		
Brakes			
Performance	1		
Hand brake	1		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			7.0 mm
Right front			7.0 mm
Left rear		-	7.0 mm
Right rear		-	7.0 mm
Spare	No		
Suspension			
Suspension performance	1		
Steering performance	/		
Shock absorbers	_		
Air Conditioning / Heater			
Operation	/		Π
Electrical / Accessories			
Head lights	1	l	
Tail lights	~		
Indicators	~		
Dashboard warning lights	V		
Wipers (front & rear) Window winder FL	•		
Window winder FR Window winder FR	<i>'</i>		
	•		
Window winder RL			-
Window winder RR			-
Rear view mirrors			
Radio (basic test only)	"		
CD (basic test only)			
Number of keys	2	1	
Central locking	•		
Remote locking	•		
Sat. nav. (basic test only)			
Reversing camera			'

Road Condition	s During Test Drive	Dry
Engine Timing N	Mechanism	Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Chris Buckley	
Published by:	Jeremy Hutchings	s
Inspection Date:	26 Nov 2025	

have read and understood
this condition quide

Panels:

Dashboard:

General Comments Noise Front Drive line .

Average Good

NAME			
NAIVIE			