

•	Report ID:	27,814,857	Version:	1
	Created:	28 Nov 2025		

Make:	Holden	Model:	Captiva 7
Body Style:	SUV	Year:	2013
Rego No.:	HAE901	Rego Expiry:	04 May 2026
WoF Expiry:	26 Jan 2026	Odometer:	225,861 Kms
Good No.:	27814857	VIN:	KL3CA26UJDB051351
Next Service:	232000	Service History:	No
liagnostic testing un ull mechanical inspe	only. Consideration is made	een driven up to 50km/ł	arts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.
	= Rust $C = C$ $\Gamma$ = Paint defect $P = Pi$	rack * = Deca in dent SC = Stor	
		S S S C	S
S SC (			S SC
			sc
S SC			S
S SC	S	SC SSC	S SC
	and blemishes may not be	displayed in the diagra	ım .
Body Inspection			
Minor stonechip	os on windscreen		
Conditions Dur	ring Body Inspection		Dry
Under Carriag	e and Under Bonnet	Inspection Comm	nents
Front wheel driv Right hand axle			
Interior Comm	nents		
	Good		
Seats:			
	Good		
Seats: Carpets: Panels:			
Carpets:	Good		

	ОК	Requires Attention	N/A
Engine			
Oil level		V	
Smoke & fumes	<b>/</b>		
Engine performance	/		
Noise	✓ ✓		
Coolant condition	<b>V</b>		
Cooling performance	<b>V</b>		
Radiator / Hoses (visual)	<b>V</b>		
Transmission			
Operation	<b>/</b>		
Noise	/		
Clutch			~
CV joints	/		
Wheel bearings	<b>/</b>		
Brakes			
Performance	/		
Hand brake	<b>/</b>		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			2.4 mm
Right front		į	5.2 mm
Left rear		4	4.5 mm
Right rear			1.4 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	<b>/</b>		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	<b>/</b>		
Electrical / Accessories		T	
Head lights	/		
Tail lights	/		
Indicators	<b>V</b>		
Dashboard warning lights			
Wipers (front & rear)	•		
Window winder FL	/		
Window winder FR	•		
Window winder RL	•		
Window winder RR	/		
Rear view mirrors	<b>/</b>		
Radio (basic test only)	<b>✓</b>		
CD (basic test only)			
Number of keys	1	1	
Central locking	<b>/</b>		
Remote locking	<b>✓</b>		
Sat. nav. (basic test only)			
Reversing camera			

Weird noise from Slight rattle from	n engine when going engine	40 km/h and up	
Road Conditions During Test Drive		Dry	
Engine Timing I	Mechanism	Timing Chain	
Evidence of Car	n Belt Replacement	Yes No Kms	
Inspected by:	Cameron Senior-Arnold		
Published by:	Janine Bell		
Inspection Date:	27 Nov 2025		
		· · · · · · · · · · · · · · · · · · ·	

I have read and understood
this condition quide

Could do with a top up of oil

NAME			

S	IG	N	ΔT	ΓIJ	R	F