

Report ID:	27,815,385	Version:	1
Created:	28 Nov 2025		


Make:	Suzuki	Model:	Swift
Body Style:	Hatchback	Year:	2005
Rego No.:	MWF964	Rego Expiry:	14 Nov 2026
WoF Expiry:	17 Jul 2026	Odometer:	212,248 Kms
Good No.:	27815385	VIN:	7AT0GK0CX19117245
Next Service:	220500	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Minor stonechips on windscreen  
Part missing out of front bumper

Conditions During Body Inspection Dry

## Under Carriage and Under Bonnet Inspection Comments

Front wheel drive  
Right front CV boot leak

## Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

## General Comments

Left taillight not working  
Rear water jets not working  
Passenger window button is missing/ can still use window from drivers button  
Remote locking doesn't work

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
Inspected by:	Cameron Senior-Arnold		
Published by:	Janine Bell		
Inspection Date:	27 Nov 2025		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	6.2 mm		
Right front	6.0 mm		
Left rear	5.7 mm		
Right rear	5.9 mm		
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights		✓	
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)		✓	
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking		✓	
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_