

•	Report ID:	27,815,448	Version:	3
	Created:	05 Dec 2025		

		Raci	c Condition Guide		
	nuer	<u> </u>	C Condition Galae	Created: 05 Dec 2	
Make:	Toyota	Model:	Hilux		
Body Style:	Utility	Year:	2014	Facine	
Rego No.:	HPJ202	Rego Expiry:	04 Jul 2026	Engine	
WoF Expiry:	18 Dec 2026	Odometer:	177,510 Kms	Oil level	
Good No.:	27815448	VIN:	MR0EZ12GX04157797	Smoke & fumes	
Next Service:	187000 Kms	Service History:	No	Engine performance	
Note: This report is	not a warranty	,		Noise	
This report is a guide	only. Consideration is made	e for age and mileage. Pa	arts have not been dismantled or	Coolant condition	
full mechanical inspe	ection prior to purchase and	d this can be arranged f	n from cold. The Vendor recommends a or an additional charge.	Cooling performance	
Key				Radiator / Hoses (visua	
S = Scratch R =	= Rust C = C	rack * = Deca	ls W = Significant scuffs	Transmission	
D = Dent PT	= Paint defect $P = Pi$	in dent SC = Stor	ne Chips	Operation	
D		P	SP	Noise	
	$\overline{}$			Clutch	
	CV joints				
	Wheel bearings				
SDPT	Brakes				
	Performance				
	Hand brake				
	Tyres (lowest observed				
	Left front				
			(Q) s	Right front	
	Left rear				
D	Right rear				
Note: some defects a	and blemishes may not be	displayed in the diagra	ım	Spare	
Body Inspection		. , , , , , , , , , , , , , , , , , , ,		Suspension	
				Suspension performa	
				Steering performance	
				Shock absorbers	
Conditions Duri	ing Body Inspection		Dry	Air Conditioning / Ho	
Under Carriage	e and Under Bonnet	Inspection Comm	ents	Operation	
	Electrical / Accessori				
	Head lights				
				Tail lights	
Interior Comm	ents			Indicators	

		Requires	
	OK	Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise	V V V		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	•		
Transmission			
Operation	/		
Noise	/		
Clutch	/		
CV joints			_
Wheel bearings	•		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread de	epth of	tyres)	
Left front		8	3.0 mm
Right front		8	3.0 mm
Left rear		8	3.0 mm
Right rear		8	3.0 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	/		L
Electrical / Accessories			
Head lights	/		
Tail lights	•		
Indicators	•		
Dashboard warning lights	•		
Wipers (front & rear)	'		
Window winder FL	/		
Window winder FR	/		
Window winder RL	•		
Window winder RR	•		
Rear view mirrors	/		
Radio (basic test only)	•		
CD (basic test only)			
Number of keys	1		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			~
Reversing camera	/		

Interior Comments		
Seats:	Average	
Carpets:	Good	
Panels:	Average	
Dashboard:	Average	
General Comments		

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		✓ Yes	No	150,012 Kms
Inspected by:	Eleoit Kumar			
Published by:	Shraddha Bhungaliya			
Inspection Date:	27 Nov 2025			

I have read and understood	k
this condition quide	

NAME			