

•	Report ID:	27,815,794	Version:	1
	Created:	03 Dec 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	~		
Engine performance	~		
Noise	/		
Coolant condition	~		
Cooling performance	~		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	/		
Noise	~		
Clutch			~
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	1		
Hand brake	✓		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		,	3.9 mm
Right front		3	3.7 mm
Left rear		3	3.3 mm
Right rear			2.6 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	✓		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	✓		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			~
Number of keys	1		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			~
Reversing camera			~
-			


Make:	Subaru	Model:	Legacy
Body Style:	Wagon	Year:	2007
Rego No.:	MBH213	Rego Expiry:	05 Apr 2026
WoF Expiry:	14 Jul 2026	Odometer:	184,645 Kms
Good No.:	27815794	VIN:	7AT0GF0BX19163436
Next Service:	184648	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a $full\ mechanical\ inspection\ prior\ to\ purchase\ and\ this\ can\ be\ arranged\ for\ an\ additional\ charge.$

Kev

ncy				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Minor stonechips on windscreen

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

All wheel drive

Interior Comments			
Seats:	Good		
Carpets:	Good		
Panels:	Good		
Dashboard:	patches and scratches on dash- Average		
General Comments			

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt	,	
Evidence of Cam Belt Replacement		✓ Yes	No	108,000 Kms
Inspected by:	Cameron Senior-A	Arnold		
Published by:	Janine Bell			
Inspection Date:	27 Nov 2025			

I have read and	understood
this condition a	uide.

NAME			

SI	GN	AT	URF	