


Make:	Nissan	Model:	Juke
Body Style:	Hatchback	Year:	2013
Rego No.:	LTD508	Rego Expiry:	31 Aug 2025
WoF Expiry:	03 Aug 2025	Odometer:	119,832 Kms
Good No.:	27815929	VIN:	7AT0DH8HX18303583
Next Service:	106,777 kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

L rear seat folding switch missing and seat belt plastic cover missing, r front moulding not secured,

Conditions During Body Inspection	Dry
-----------------------------------	-----

**Under Carriage and Under Bonnet Inspection Comments**
**Interior Comments**

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

**General Comments**

Remote key not working, middle console torn, aircon not cold,L head high beam not working,service overdue

Road Conditions During Test Drive	Dry	
Engine Timing Mechanism	Timing Chain	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
Inspected by:	Marlon Espena	
Published by:	Marlon Espena	
Inspection Date:	02 Dec 2025	

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

Report ID:	27,815,929	Version:	1
Created:	02 Dec 2025		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level		✓	
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front		5 mm	
Right front		5 mm	
Left rear		6 mm	
Right rear		6 mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation		✓	
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)			✓
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking			✓
Sat. nav. (basic test only)			
Reversing camera	✓		

SIGNATURE \_\_\_\_\_