

Report ID:	27,816,132	Version:	2
Created:	16 Dec 2025		

Basic Condition Guide			Report ID:	27,816,132	Ve	rsion: 2		
	omer			Created:	16 Dec 2025			
Make:	Suzuki	Model:	Swift				Requires	
Body Style:	Hatchback	Year:	2018	For action a		OK	Attention	N/A
Rego No.:	QCD846	Rego Expiry:	09 Jan 2026	Engine				
WoF Expiry:	11 Jul 2026	Odometer:	80,560 Kms	Oil level		/		
Good No.:	27816132	VIN:	7AT0GK0CX23111857	Smoke & fu		/		
Next Service:	90,570kms	Service History:	No	Engine per	formance	/		
Note: This report is	, ,	,		Noise	1	/		
This report is a guide	only. Consideration is made	e for age and mileage. Pa	arts have not been dismantled or h from cold. The Vendor recommends a	Coolant co		/		
full mechanical inspe	ection prior to purchase and	d this can be arranged f	or an additional charge.	Cooling pe		/		
Key					Hoses (visual)	/	ļ	
	= Rust $C = C$		3	Transmission				
D = Dent PT	Γ = Paint defect $P = Pi$	in dent SC = Sto	ne Chips	Operation		/		
		D D		Noise		/		
				Clutch				
			W	CV joints		/		
SC (Wheel bearings 🗸				
$\neg \neg \neg$	18			Brakes Performance				
						/		
P			Hand brake					
			Tyres (lowest observed tread depth of tyres)					
			Left front				5 mm	
			Right front				2 mm	
	\leftarrow	D D		Left rear				4 mm
P P P						3 mm		
	and blemishes may not be	displayed in the diagra	am	Spare		No		
Body Inspection				Suspensio	n	1	ı	
RF tyre tread cr	acks and inner edge s	scalloped. Tools ar	nd spare tyre missing.	Suspension	performance	~		
					erformance	/		
				Shock abso	orbers			
Conditions During Body Inspection			Air Conditioning / Heater					
Under Carriage and Under Bonnet Inspection Comments				Operation		/		
				Electrical /	Accessories			
				Head lights	5	~		
				Tail lights		~		
Interior Comm	nents			Indicators		/		
Seats:	Good			Dashboard	warning lights	1		
Carpets:	Good			Wipers (fro	nt & rear)	~		
Panels:	Good			Window w	inder FL	~		
Dashboard:	Good			Window w	inder FR	~		
General Comn	nents			Window w	inder RL	/		
						1		1

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Marlon Espena	
Published by:	Marlon Espena	

I have read and understood this condition guide:

Inspection Date: 16 Dec 2025

FWD.

NAME			

SIGNATURE		

•

1

1

•

Window winder RR Rear view mirrors

Radio (basic test only) CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)