


Make:	Nissan	Model:	Leaf
Body Style:	Hatchback	Year:	2016
Rego No.:	MFB93	Rego Expiry:	16 Mar 2026
WoF Expiry:	24 Dec 2025	Odometer:	127,636 Kms
Good No.:	27816496	VIN:	7AT0DH8KX19213505
Next Service:	137,550kms	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Right wing mirror casing broken.

Under Carriage and Under Bonnet Inspection Comments

Seats:	Good
Carpets:	Average
Panels:	Cargo tray missing.
Dashboard:	Good

Full electric Leaf hatch.
SOH 64%

I have read and understood
this condition guide:

NAME _____

SIGNATURE

	OK	Requires Attention	N/A
Engine			
Oil level			✓
Smoke & fumes			✓
Engine performance	✓		
Noise			✓
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	5.0 mm		
Right front	5.0 mm		
Left rear	5.0 mm		
Right rear	6.0 mm		
Spare	N/A		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)	✓		
Reversing camera	✓		