

•	Report ID:	27,817,865	Version:	1	
	Created:	02 Dec 2025			

mm mm mm mm

		Pooi	a Condition Cuida	Report ID:	27,817,865	Ve	rsion:	1	
	nue	S Dasi	c Condition Guide	Created:	02 Dec 2025				
Make:	Toyota	Model:	Camry			01/	Requi		
Body Style:	Sedan	Year:	2008	Engino		OK	Attent	lion	N,
Rego No.:	ERJ404	Rego Expiry:	09 Jan 2026	Engine		V		_	
WoF Expiry:	26 Aug 2026	Odometer:	263,173 Kms	Oil level		<i>'</i>			
Good No.:	27817865	VIN:	6T153BK400X064030	Smoke & fu		-		_	
Next Service:	253000	Service History:	No	Engine per Noise	Tormance	V			
Note: This report is not a warranty					1942	V			
This report is a guide	only. Consideration is made	e for age and mileage. P	arts have not been dismantled or	Coolant co		/		_	
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					rformance	/			
Key					Hoses (visual)	/			
	= Rust $C = C$. J	Transmiss Operation	ion				
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips S PT SC S SC SC S PT						/			
						/			
				Clutch				_	(
S SC S PT SC						/			
					rings	/			
A				Brakes		,			
			SC	Performan	ce	/			
				Hand brake	2	/			
S PT SC				Tyres (lowest observed tread depth of tyres)					
				Left front				4	.6
SP						4.8			.8
								3	.7
S PT SC SC S				Right rear				5	.8
Note: some defects and blemishes may not be displayed in the diagram				Spare Yes					
Body Inspecti	on Comments			Suspensio	n				
Minor stonechip	os on windscreen			Suspension	n performance	V			
Plastic piece m	issing out of front bur	nper		Steering pe	erformance	1			
				Shock abso	orbers	1			
Conditions Du	ring Body Inspection		Dry	Air Condit	ioning / Heater	,			
Under Carriag	je and Under Bonnet	Inspection Comm	nents	Operation		V			
Front wheel driv				Electrical /	'Accessories			'	
Slight oil leak around oil sump Underbody cover damaged				Head lights	5	V			
Underbody Cove	er damaged			Tail lights		1			
Interior Comn	nents			Indicators		1			
Seats:	Good				warning lights	1		_	
Carpets:	Good			Wipers (fro		1			
Panels:	Good			Window w		1			
Dashboard:	very sticky dash-	Average		Window w		1			
General Comr				Window w		1		\dashv	

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Cameron Senior-A	Arnold
Published by:	Janine Bell	
Inspection Date:	28 Nov 2025	

have read and understood
his condition quide

Due for service

NAME			

SIGNATURE		

•

1

1

•

Window winder RR Rear view mirrors

Radio (basic test only) CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera