

Report ID:	27,817,947	Version:	3
Created:	04 Dec 2025		

		Paci	ic Condition Guide	Report ID: 2
	urner	S Dasi	——————————————————————————————————————	Created: 0
Make:	Toyota	Model:	Caldina	
Body Style:	Wagon	Year:	2005	
Rego No.:	GQA905	Rego Expiry:	04 Jan 2026	Engine
WoF Expiry:	03 Dec 2026	Odometer:	242,473 Kms	Oil level
Good No.:	27817947	VIN:	7AT0H624X12024512	Smoke & fun
Next Service:	252,478kms	Service History:	No	Engine perfo
		Service History.	110	Noise
<b>Note: This report is not a warranty</b> This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or				
	indertaken. The vehicle has b bection prior to purchase an		h from cold. The Vendor recommends a for an additional charge.	Cooling perf
Кеу				Radiator / Ho
S = Scratch	R = Rust $C = C$	rack *= Deca	lls W = Significant scuffs	Transmissio
D = Dent F	PT = Paint defect P = P	in dent SC = Sto	ne Chips	Operation
PT P	sc	D PT P	SC P	Noise
				Clutch
				CV joints
	NA UN			Wheel bearing
sc 6				Brakes
	1195 11			Performance
			S	Hand brake
S P SC	HR W			Tyres (lowes
				Left front
			(Q) P	Right front
				Left rear
P	S	P DP	SSP	Right rear
lote: some defect	s and blemishes may not be	displayed in the diagra	am	Spare
	ion Comments			Suspension
				Suspension
				Steering per
				Shock absort
Conditions Du	uring Body Inspection		Dry	Air Conditio
	ge and Under Bonnet	Inspection Comm	,	Operation
	<b>3</b> · · · · · · · · · · · · · · · · · · ·			Electrical / A
				Head lights
				Tail lights
Interior Com	ments			Indicators
Seats:	Good			Dashboard v
Carpets:	Good			Wipers (fron
Panels:	Average			Window win
Dashboard:	Good			Window win
General Com				
	inents			Window win
Rough idle.				Window win
				Rear view mi

		Requires		
	OK	Attention	N/A	
Engine		_	1	
Oil level	_	<b>/</b>		
Smoke & fumes	/			
Engine performance	•			
Noise	•			
Coolant condition	<b>/</b>			
Cooling performance	<b>/</b>			
Radiator / Hoses (visual)				
Transmission		ı		
Operation	/			
Noise	/			
Clutch			<b>/</b>	
CV joints	<b>✓</b>			
Wheel bearings	<b>/</b>			
Brakes				
Performance	<b>/</b>			
Hand brake	<b>/</b>		<u> </u>	
Tyres (lowest observed tread d	epth of	tyres)		
Left front			6.5 mm	
Right front			5.5 mm	
Left rear			3.5 mm	
Right rear			3.5 mm	
Spare	Yes			
Suspension				
Suspension performance	<b>✓</b>			
Steering performance	<b>✓</b>			
Shock absorbers	V			
Air Conditioning / Heater				
Operation	<b>✓</b>			
Electrical / Accessories				
Head lights	~			
Tail lights	/			
Indicators	<b>V</b>			
Dashboard warning lights	<b>V</b>			
Wipers (front & rear)		~		
Window winder FL	1			
Window winder FR	1			
Window winder RL	1			
Window winder RR		~		
Rear view mirrors	<b>✓</b>			
Radio (basic test only)	/			
CD (basic test only)	/			
Number of keys	1			
Central locking	/			
Remote locking			·	
Sat. nav. (basic test only)				
Reversing camera	1			
2.29 2				

I have read and understood this condition guide:

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Inspection Date: 28 Nov 2025

Engine Timing Mechanism

Inspected by:

Published by:

N	Δ	M	F

LukaAjitvan Woerden

Tessa Bagrie

Dry

Timing Chain

No

Yes

SIGNATURE

Kms